ORIGINAL

FOREST LAWN PARTS DEPOT

4215 - 35th STREET S.E.
CALGARY, ALBERTA T2B 3C6
(403) 272-2611 / 272-3343 FAX: 248-4804
Email: flapp@telusplanet.net

[redacted]

WWW.FLAPP.CA

REFERENCE # 275980 DATE 03/17/22 03:36 PM

P.O. #

CUSTOMER # [redacted]

SHIP TO [redacted]

INVOICES OVER 30 DAYS OUTSTANDING ARE SUBJECT TO A CHARGE OF 1.5% (18% PER ANNUM).

Page 1

SALESMAN	TYPE OF SALE	TAX CODE	SHIP VIA
1 - 1 tbh	COUNTER SALE	AB 271-2717	

QUANTITY	PART NUMBER AND DESCRIPTION	UNIT PRICE	EXTENSION
1	300-660428 1U-ENGINE ASSEMBLY; Stk# 150087; A320 VIN# JM1BL1VF8C1518164; NOTES 2.0,AT,FWD,WONT START ; Requested:2010 MAZDA 3; MAZDA 3 10-11 2.0L, standard emissions (VIN F, 8th digit); Q:339926	700.00	700.00
	DISCOUNTED TO CHANGE TIMING COVER		
	TAX		35.00
	TOTAL		735.00

Thank you for your purchase,GST#873131619RT

			Discount		.00
Cash	.00	Check	.00	Sub Total	700.00
Charge	.00	C/Card	735.00	Taxable	700.00
D/Card	.00	GST	35.00	Prov Tax	.00

RECEIVED BY _____

Willowridge Auto Service

9900 Fairmount Drive SE
Calgary, AB
T2J 0S4
Phone: 403.271.2717 Email: service@willowridgeauto.ca
GST# 105699045

Invoice

[redacted]

Plate	AB CJW1356
Description	Silver 2010 Mazda 3 i L4 2.0L 2000CC 122CID VIN F
VIN	JM1BL1SF3A1266468
Odometer	172,949 In / 172,951 Out
Invoice Date	1/27/2022 3:15 PM
Appointment	1/27/2022 1:16 PM
Promised	1/28/2022 4:30 PM

Inspection

Willowridge Auto Service
Clunk in rear end over bumps

Service

Replaced both rear shocks and mounts
Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor		$82.50 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
19-119526 - BILSTEIN - B4 OE REPLACEMENT	2 Unit	$151.44 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
SM5619 - SHOCK MOUNT	2 Unit	$49.74 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
	Sub	**$283.68**

Total Parts		$201.18
Total Labor		$82.50
Total Before Taxes & Miscellaneous Charges		$283.68
(*) Shop Supplies*		$0.00 G
(E) Environmental Disposal Charge*		$0.00 G
(G) Canadian Goods and Services Tax (GST)	5 %	$14.19
Grand Total		**$297.87**

Potter, Terry paid $297.87 by Visa
1/27/2022 3:16 PM Card #: XXXXXXXXXXXX9980 Entry Method: Chip Type: Sale Amount: 297.87
Terminal: 51719 Transaction: e3ee8160-6c14-4487-a00c-92ae8e16ec68 Authorization: 08311I Result: Approved
AID: A0000000031010 TC: TC: 6FAD51E0D9292002 TVR: 8080008000 TSI: 7800

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.

Thanks for the Business!
I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature:_____

Willowridge Auto Service

9900 Fairmount Drive SE
Calgary, AB
T2J 0S4
Phone: 403.271.2717 Email: service@willowridgeauto.ca
GST# 105699045

Invoice

[redacted]

Plate AB CJW1356
Description Silver 2010 Mazda 3 i L4 2.0L 2000CC 122CID VIN F
VIN JM1BL1SF3A1266468
Odometer 175,558

Invoice Date 3/22/2022 10:53 AM
Appointment 3/9/2022 9:50 PM
Promised 3/10/2022 4:30 PM

Inspection

Willowridge Auto Service
oil pressure light was flashing while driving or idling, pulled over checked level was fine , then oil light stayed on solid and power steering light came on then vehicle died on highway cranks but does not start ?? Towed to shop

Service

Loaner Car 03/09/22 09:45am to 03/10/22 07:00 am
Provide Kia Soul (BRW-8505) as a loaner car for customer during service appointment. Smoking and pets are not allowed in vehicle. Customer is responsible for any and all tickets incurred while in possession of loaner. Vehicle will be sanitized upon each customer transfer. Fee is to cover fuel, insurance and maintenance costs.

Loaner Service Fee ($10 Per Day)	$0.00 / Hour	$10.00 G
	Discount	**($10.00)**
	Sub	**$0.00**

Diagnose Oil Pressure Light On
Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Labor		$37.50 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
	Sub	**$37.50**

confirmed engine failure camshaft broken off engine needs to be replaced

Supply Parts For Engine Replacement - Has 47,000km
Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

PPC11551 - Celsius Long Life Coolant 1L	4 Unit	$23.28 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
FC65354 - Pilot Bearing	1 Unit	$8.47 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
MS19582 - MAHLE ORIGINAL - Exhaust Manifold Gasket	1 Unit	$32.32 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
	Sub	**$64.07**

Supply Spark Plug(s)
Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

990083 - NGK Laser Iridium Spark Plugs - OEM	4 Unit	$57.04 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
	Sub	**$57.04**

Thermostat Housing and Gasket
Includes removal and replacement of thermostat housing. Clean all surfaces and replace thermostat gasket. Fill system with premixed coolant and bleed system. Run vehicle and check fluid level. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

85994 - Thermostat Housing and Gasket	1 Unit	$34.42 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
	Sub	**$34.42**

Synthetic Oil and Filter
Drain and refill with premium synthetic engine oil, change engine oil filter and lubricate chassis grease fittings and friction points as required. Check and top off fluid levels, additional charges may apply where fluids are required. Complete a complementary 40 point vehicle inspection, rotate tires as required.

S020473X1M - Motor Oil Purezone 0W20 Synthetic Dexos 1L	4.2 Unit	$40.70 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
DL3614 - Oil Filter 8-51348	1 Unit	$3.87 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
	Sub	**$44.57**

65/16. Manual Transmission Fluid Service
Includes: Evacuate and/or drain fluid. Fill transmission with manufacturers recommended fluid to proper level. Road test, noting transmission operation.

20047 - Lucas Gear Oil 75W90 Synthetic	1 Unit	$17.48 G
Technician: Gerry Groot / Service Advisor: Terry Potter		
	Sub	**$17.48**

Maintenance Suggestions:
Service Manual transmission every 2 years or 48,000 km

Total Parts		$217.58
Total Labor		$37.50
Total Before Taxes & Miscellaneous Charges		$255.08
(*) Shop Supplies*		$0.00 G
(E) Environmental Disposal Charge		$1.00 G
(G) Canadian Goods and Services Tax (GST)	5 %	$12.81
Grand Total		**$268.89**

Total discounts applied is $10.00

Potter, Terry paid $268.89 by Visa
3/22/2022 10:53 AM Card #: XXXXXXXXXXXX9980 Entry Method: Chip Type: Sale Amount: 268.89
Terminal: 51719 Transaction: 2a4a8365-9450-4f59-8a06-465818f663e1 Authorization: 09745I Result: Approved
AID: A0000000031010 TC: TC: 068758165B7CE2DD TVR: 8080008000 TSI: 7800

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.

Thanks for the Business!
I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature:_____