

**A&M MOBILE MECHANIC LTD**

520 - 35 AVE NE  
CALGARY AB T2E 2K8  
+14032350005  
<http://www.ammobilemechanic.com>  
GST/HST Registration No.: 85683 9600 RT0001

**INVOICE****BILL TO****INVOICE # 22586****DATE 2026/01/28**

<b>YR/MAKE/MODEL</b>	<b>TRANNY/ODOMETER</b>	<b>VIN</b>
2017 BUICK ENCLAVE	AUTO/272779	5GAKVBKD2HJ257853

SERVICE	QTY	RATE	AMOUNT
CUSTOMER REPAIR REQUEST: ABS LIGHT	1	0.00	0.00
LABOUR: TEST DROVE CAR AND WOULD VIBRATE BETWEEN 2-4000 RPM AND ABS AND TRACTION LIGHT WOULD TURN ON. SCANNED CAR AND GOT CODE C0505, REAR RIGHT REAR WHEEL SENSORS. REMOVED ABS SENSOR AND PUT CAMERA INSIDE HUB AND SAW WHEEL BEARING MAGNETS DAMAGED. REMOVED AND REPLACED WHEEL BEARING, CAR IS DRIVING GOOD NOW AND NO CODES.	1	115.00	115.00
REAR WHEEL BEARING	1	170.12	170.12
SHOP SUPPLIES	1	15.00	15.00

NOTE: Warranty applies on OEM part only for part and labor.  
Aftermarket part warranty covers the part only. Please visit us  
again within 50 km to re-torque your wheels, and re-check your  
car.  
LIKE US ON FACEBOOK.

SUBTOTAL	300.12
GST/HST @ 5%	15.01
<b>TOTAL</b>	<b>315.13</b>
PAYMENT	315.13
BALANCE DUE	<b>\$0.00</b>