

33743

**Burnt Timber Auto LTD.**  
Site 2, Comp 10, RR 2  
Crossfield, AB. T0M 0S0  
Phone: 403-827-6027 Fax: 403-637-7021  
Burnttimberauto@hotmail.com

**INVOICE**

**6242**

Printed Date: 08/27/2024 Work Completed: 06/12/2024

2001 Toyota - Camry Solara SLE - 3L, V6 (182CI) VIN(F)

Lic #: Odometer In : 312687

VIN #: 2T1FF22P7 1C866798



Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
gas cap 7031719	1.00	13.06	13.06	replace Cam seal, cank seal water pump	5.50	660.00
water pump/ T-belt kit comes with idler and tensioner TKT024	1.00	542.13	542.13	T-belt all 3 drive belt replaced timing belt kit with water pump, replace both cam seals and crank seal, replaced both drive belts.		
Cam seal 2118533	2.00	4.70	9.40			
crank seal 2111010	1.00	6.00	6.00			
power steering belt 25040347	1.00	43.57	43.57			
Alternator belt 25060407	1.00	43.72	43.72			
bracket 917189	1.00	93.74	93.74			
Shop Supplies			14.12			

Org. Estimate 1,497.03 Revisions 0.00 Current Estimate 1,497.03

<b>Labor:</b>	<b>660.00</b>
<b>Parts:</b>	<b>765.74</b>
<b>SubTotal:</b>	<b>1,425.74</b>
<b>Tax:</b>	<b>71.29</b>
<b>Total:</b>	<b>1,497.03</b>
<b>Bal Due:</b>	<b>\$0.00</b>

[ Payments - Cash - \$1,497.03 ]

Vehicle Received: 2024-06-11

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is one years or 10,000km whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

wheels should always be re-torque after 100-150 km ( n/c to re-check )

THIS INVOICE NEEDS TO BE PAID WITHIN 48H OF PICKING UP CAR/ INTEREST CHARGE WILL BE APPLIED

GST# 77844333RT0001

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: [Burnttimberauto@hotmail.com](mailto:Burnttimberauto@hotmail.com)

**Burnt Timber Auto LTD.**  
 Site 2, Comp 10, RR 2  
 Crossfield, AB. T0M 0S0  
 Phone: 403-827-6027 Fax: 403-637-7021  
 Burnttimberauto@hotmail.com

**INVOICE**

**6197**

**INVOICE**

Printed Date: 05/17/2024 Work Completed: 05/17/2024

2001 Toyota - Camry Solara SLE - 3L, V6 (182CI) VIN(F)  
 Lic # : Odometer In : 309863

VIN # : 2T1FF22P7 1C866798

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
---------------------------	-----	------	-----	-------------------	-------	-----

Org. Estimate	136.49	Revisions	1,086.03	Current Estimate	1,222.52
---------------	--------	-----------	----------	------------------	----------

Labor:	563.99
Parts:	606.89
<b>SubTotal:</b>	<b>1,170.88</b>
Tax:	58.54
<b>Total:</b>	<b>1,229.42</b>
<b>Bal Due:</b>	<b>\$1,229.42</b>

[ Payments - ]

Vehicle Received: 2024-05-16

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is one years or 10,000km whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

wheels should always be re-torque after 100-150 km ( n/c to re-check )

THIS INVOICE NEEDS TO BE PAID WITHIN 48H OF PICKING UP CAR/ INTEREST CHARGE WILL BE APPLIED

GST# 77844333RT0001

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: [Burnttimberauto@hotmail.com](mailto:Burnttimberauto@hotmail.com)

**Burnt Timber Auto LTD.**

Site 2, Comp 10, RR 2  
 Crossfield, AB. T0M 0S0  
 Phone: 403-827-6027 Fax: 403-637-7021  
 Burnttimberauto@hotmail.com

**INVOICE**

**6197**

**INVOICE**

Printed Date: 05/17/2024 Work Completed: 05/17/2024

2001 Toyota - Camry Solara SLE - 3L, V6 (182CI) VIN(F)  
 Lic # : Odometer In : 309863

VIN # : 2T1FF22P7 1C866798

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext	
engine oil synthtic Blend 530	5.00	6.50	32.50	Performed Maintenance inspection, completed engine oil drain and refill, replace oil filter. check for suspension/ front end play check lights or any other safety issues completed Frnt pads 70% Rear pads 25-30% tires Front: 4/32 Tires Rear: 4 /32  rims mismatch timing belt and drive belt should be done with cam and crank seal power steering high pressure hose front struts ( coil sping broken ) Right rear control arm bushing worn out front sway bar bushing noisy/ loose front rotors rusty but lots of pads RF shaft shaft boot torn open Steering rack sweating (not a big concern currently)	1.20	119.99	
engine oil filter 1348	1.00	12.49	12.49				
synthetic trans fluid MV	6.00	10.96	65.76				
left rear wheel bearing NBR930370	1.00	203.54	203.54				
premium rear brake pads SG7701X	1.00	81.77	81.77				
premium rear rotors 74886216	2.00	52.26	104.52				
MaxtrekMAXIMUS M2 - 92V 72 205/60R16 MAX3344	1.00	94.72	94.72				
Shop Supplies			11.59				
					TRANSMISSION OIL PAN GASKET &/OR FILTER - Remove & Replace	1.60	192.00
					LEFT REAR WHEEL BEARING - Remove & Replace - Rear,Hub & Bearing Assy,One Side [Includes: Replace Inner and/or Outer Bearings, Cups, Seals and repack (where applicable).]	0.80	96.00
				Replace rear pads and Rotors	1.00	120.00	
				Replace Rear brake pad linings and replace rear brake disc rotors. Clean and lubricate brake calipers and slide mechanisms. Check and fill brake fluid. Bleed air from system. Road test vehicle.			
				supply replace one spare tire	0.30	36.00	

Email Address: [Burnttimberauto@hotmail.com](mailto:Burnttimberauto@hotmail.com)