



Phone: 403-263-0225

3832 16th Street SE
Calgary, AB T2G 3R7

Email: service@ladsauto.com

NAPA AUTOPRO Store# 4822

GST# R10292968

Estimate of Deferred Work



Invoice # 77772

Work Order # 144467

Service Advisor Priscilla Hill

Technician Reece Daly

Description Silver 2003 Toyota 4Runner Limited V8 4.7L
4663CC 285CID
VIN JTEBT14R430014479
Odometer 392,810

Invoice Date 8/14/2026 3:45 PM

Appointment 8/14/2026 10:00 AM

Promised 8/14/2026 5:00 PM

Deferred Service

SUSPENSION BALL JOINT & CONTROL ARM - RIGHT FRONT LOWER, REPLACE (REQUIRES WHEEL ALIGNMENT)

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Remove & Replace F Control Arm - One Side

\$524.01 G

Technician: Reece Daly / Service Advisor: Priscilla Hill

131168 - Control Arm with Ball Joint - Front Right Lower

1 Unit

\$364.23 / Unit

\$364.23 G

Technician: Reece Daly / Service Advisor: Priscilla Hill

Sub \$888.24

SUSPENSION SWAY BAR LINK & BUSHINGS - REAR REPLACE (BUSHINGS)

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Remove & Replace R Stabilizer Bar Bushing - Both

\$314.41 G

Technician: Reece Daly / Service Advisor: Priscilla Hill

4881514140 - Toyota - Suspension Stabilizer Bar Bushing
(Rear)

2 Unit

\$86.11 / Unit

\$172.22 G

Technician: Reece Daly / Service Advisor: Priscilla Hill

4883060030 - Toyota - Suspension Stabilizer Bar Link
(Driver Rear)

1 Unit

\$192.68 / Unit

\$192.68 G

Technician: Reece Daly / Service Advisor: Priscilla Hill

Sub \$679.31

LADS AUTO WHEEL ALIGNMENT SERVICE - (INCLUDES: FRONT ADJUSTMENTS ONLY) (MAY REQUIRE STEERING ANGLE RESET OR ADAS CALIBRATION)

Includes: Inspection of front end components, ride height. Adjust tire pressures as necessary. Install alignment equipment onto wheels. Adjust front toe-in on all models, alignment and reference on front and rear wheels. Extra charges will apply for camber and/or caster adjustments (front or rear) or rear toe adjustment.

Service

\$192.14 G

Technician: Reece Daly / Service Advisor: Priscilla Hill

Sub \$192.14

EXHAUST HEAT SHIELD - REMOVE (RATTLES)

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

RE-TORQUE WHEELS - 83 FT/LBS

Re-torque wheels as necessary.

Total Parts

\$729.13

KEEPING CANADIANS ON THE ROAD SINCE 1985



Phone: 403-263-0225

3832 16th Street SE
Calgary, AB T2G 3R7

Email: service@ladsauto.com

NAPA AUTOPRO Store# 4822

GST# R10292968

Total Labor		\$1,030.56
Total Before Taxes & Miscellaneous Charges		\$1,759.69
(SE) Materials and Consumables / Hazardous Waste Disposal Fee		\$166.17 G
(G) Canadian Goods and Services Tax (GST)	5 %	\$96.30
Grand Total		\$2,022.16

This Estimate is based on visual inspection, and does not include additional items which may be required after disassembly. Occasionally, after work is started, worn, broken, or damaged parts maybe discovered which were not evident upon the initial inspection. Prices on parts and labor are current and subject to change. All parts are assumed to be New Part not provided by the original equipment manufacturer unless otherwise noted. Estimates are valid for 30 days.

Date_____ Prepared By_____