

MECHANICAL FITNESS ASSESSMENT

As required by Vehicle Inspection Regulation (A/R 211/2006)

Dealer: CANYON CREEK TOYOTA

AMVIC Licence Number:

Address: 370 CANYON MEADOWS DR SE CALGARY AB T2J7C6

VEHICLE INFORMATION

Year: 2015

Make: NISSAN

Model: PATHFINDER

Previous Province of Registration: AB

Vehicle Identification Number: 5N1AR2MMXFC691401

Odometer Reading: 85334

☒ (km / mi) ☐

☐ Truck ☐ Motorcycle ☐ Bus ☐ Van ☒ Light Truck ☐ Auto ☐ Motorized RV ☐ Other

Please check mark (✓) each item as C=Complies or N=Non-Compliant. If item is Not Applicable indicate as N/A in the C column

Powertrain	C	N
Accelerator	✓	
Fuel System	✓	
Exhaust	✓	
Transmission	✓	
Front/Rear/Spindles Axles	✓	
Clutch	N/A	
Fluid Levels (power steering, brake)	✓	
CV Joints	✓	

Lamps	C	N
Head Lamp Hi Beam	✓	
Head Lamp Lo Beam	✓	
Head Lamp Location	✓	
Daytime Running Lamps	✓	
Tail Lamps	✓	
Brake Lamps	✓	
Turn Signal Lamps	✓	
Hazard Warning Lamps	✓	
Licence/Plate Lamp	✓	
Back-up Lamps	✓	

Instruments	C	N
Speedometer/Odometer	✓	
Indicator Lamps	✓	
Horn	✓	
Hi Beam Indicator	✓	

Brakes	C	N
Parking/Emergency Brake	✓	
Hydraulic System	✓	
Vacuum System	✓	
Drum Brakes	N/A	
Disc Brakes	✓	
Shoes/Pads	✓	
Anti-Lock (if OEM equipped)	✓	

Steering	C	N
Steering Lash	✓	
Steering Linkage	✓	
Rack & Pinion	✓	
Power Steering System	✓	
King Pin	N/A	
Ball Joints	✓	

Suspension	C	N
Leaf springs	N/A	
Struts and Shocks	✓	
Coil spring	✓	
Torsion Bar	N/A	
Independent/Multilink Rear	✓	
Computer Controlled	N/A	

Diagnostic	C	N
Diagnostic Trouble Codes	✓	

Frame & Body	C	N
Hood Latch	✓	
Door Latches & Hinges	✓	
Bumpers	✓	
Windshield Wipers & Washer	✓	
Rear Wiper & Washer	✓	
Windshield	✓	
Windows	✓	
Defrost/Heaters	✓	
Mirrors	✓	
Seats	✓	
Seat Belts/Airbags	✓	
Mudguards	✓	
Window Glazing	✓	
Structural Integrity	✓	

Tires & Wheels	C	N
Tread Depth	✓	
Tread Section	✓	
Sidewalls	✓	
Wheels	✓	

Electrical	C	N
Wiring	✓	
Battery	✓	
Switches	✓	
Alternator	✓	

Technician Comments

Front brakes pads 10MM, Rear brakes pads 9MM
Tires Front and Rear at 7/32

This is to certify that I have assessed the vehicle described above in accordance with the Traffic Safety Act, Vehicle Equipment Regulation (A/R 122/2009). By signing this assessment, I verify the contents of this document are true and correct.

Signature of Certified Journeyman Technician:

[Signature]

Technician Name (Print): JOSE GUEVARA

Technician Trade Certificate Number: 167896A

Date: MAY 6 2021

This assessment expires 120 days after the date it was issued.

I, the buyer of this vehicle, acknowledge receipt of this assessment.

[Signature]

Signature of Salesperson

Tyler Low

Salesperson (Print)

06/05/21

Date

Oil & Filter Service Inspection Report



TOYOTA

LIC. PLATE #: _____ RO #: 481171



YEAR/MAKE/MODEL: 15 Pathfinder

MILEAGE: 95,727 kms

CUSTOMER NAME: _____

VIN: 691401

Driver's floor mat quantity checked & securely fastened? ☐



Comments: _____

☒ Checked and requires no attention

☐ Attention suggested

☐ Requires immediate attention

Please check ☒

Please circle

Lights and Accessories	☒ ☒ Headlights	▶ Left	Right	☒ ☒ Reverse lights	▶ Left	Right		
	☒ ☒ Turn signal lights	▶ Front L / R	Rear L / R	Side L / R	☒ ☒ Interior lights	▶ Mirror	Front	Rear
	☒ ☒ Hazard lights	▶ Front	Rear	☒ ☒ Licence plate lights	▶ Left	Centre	Right	
	☒ ☒ Taillights	▶ Left	Right	☒ ☒ Wiper blades	▶ Left	Right	Rear	
	☒ ☒ Brake lights	▶ Left	Right	Centre	☒ ☒ Windshield washers	▶ Left	Right	Rear
	☒ ☒ Fog lights	▶ Left	Right	☒ ☒ Horn				
	☒ ☒ Cargo/trunk lights			☒ ☒ Locks, latches, hinges	▶ Lubricated			

Under Hood	☒ Engine oil level upon arrival		☒ Washer fluid	▶ Low	
	☒ Coolant	▶ Low Leaks	☒ Auto. transmission fluid	▶ Low	
	☒ Brake fluid	▶ Low Leaks	☒ Belts and hoses	▶ Cracked	Frayed
	☒ Engine air filter	▶ Restricted	☒ Power steering fluid	▶ Low	


Under-carriage	☒ Fluid leaks
	☒ Exhaust system
	☒ Damage

Wipers Inspected ☐ Winter ☒ All Season Driver ☒ Passenger ☒ Rear ☒

Tires	Front driver (Left)	▶ Air pressure	Before: <u>29</u> PSI	After: <u>33</u> PSI	▶ Tread depth	☒	☒
		▶ Wear pattern	☒ Normal	Abnormal – State condition (A,B,C,D): _____			
	Rear driver (Left)	▶ Air pressure	Before: <u>29</u> PSI	After: <u>33</u> PSI	▶ Tread depth	☒	☒
		▶ Wear pattern	☒ Normal	Abnormal – State condition (A,B,C,D): _____			
	Front passenger (Right)	▶ Air pressure	Before: <u>29</u> PSI	After: <u>33</u> PSI	▶ Tread depth	☒	☒
		▶ Wear pattern	☒ Normal	Abnormal – State condition (A,B,C,D): _____			
	Rear passenger (Right)	▶ Air pressure	Before: <u>29</u> PSI	After: <u>33</u> PSI	▶ Tread depth	☒	☒
		▶ Wear pattern	☒ Normal	Abnormal – State condition (A,B,C,D): _____			
	Spare	▶ Air pressure	Before: <u>49</u> PSI	After: <u>60</u> PSI	▶ Tread depth	☒	☒
		▶ Wear pattern	☒ Normal	Abnormal – State condition (A,B,C,D): _____			
Rotation required? ☐ Yes ☒ No							

Tread depth:
☒ 6/32" or more
☐ 4 - 5/32"
☐ 3/32" or less

Abnormal Wear Patterns



Tires Inspected ☒ All Season ☐ Winter ☐ Summer

TECHNICIAN SIGNATURE: 120190 DATE: 12/13/21

CUSTOMER COPY

COTCH-LSCTE-50



VENTURE
MOTORWORKS

Venture Motorworks
AMVIC B2035650
Vehicle Inspection Facility Licence
20706
GST Number 736416470RT0001
416 28 Street NE
Calgary, AB T2A 6T3

Invoice #16059

Created: 8/21/2023
Invoiced: 8/22/2023
Payment Term: On Receipt
Service Writer: Shawn Gillespie

2015 Nissan Pathfinder SL

VIN: 5N1ANR2MMXFC691401
Kilometers In: 115,132
Kilometers Out: 115,132

Recommendations

Wiring to rear hatch handle is broken - repaired the wire.

Chrome strip is broken, recommend replacement of chrome strip and assembly.

Diagnose & Advise Rear Hatch Not Opening

Description	HRS	Subtotal
1 Diagnose & Advise - First Hour <i>Note: The first hour of diagnostic time has been discounted to \$95 per hour. Diagnostic time in excess of the first hour will be charged at the standard shop rate of \$149 per hour.</i>	1	\$95.00

We will not exceed the authorized time without your express permission.

GST (5%): \$4.75 **Total: \$99.75**

Thank you for your business. PLEASE RETURN WITHIN 100 KM TO HAVE WHEELS RETORQUED. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Vehicles not collected within 7 calendar of work being completed will be charged a daily storage fee of \$50.

Signature _____

Parts	\$0.00
Labor	\$95.00
Subtotal	\$95.00
GST	\$4.75
PST	\$0.00
HST	\$0.00
Grand Total	\$99.75
Paid To Date	(\$99.75)

REMAINING BALANCE \$0.00

Payments

8/22/2023 \$99.75




Venture Motorworks

416 28 Street NE
Calgary, AB T2A 6T3
403-910-6259

info@venturemotorworks.ca
Venturemotorworks.ca

Invoice



Description 2015 Nissan Pathfinder S/Sv/SI/Plat 3.5L V6 F
DOHC 24V
VIN 5N1AR2MMXFC691401
Odometer 137,821 In / 137,825 Out
Invoice Date 9/23/2025 3:50 PM

Invoice # 100726
Work Order # 11120
Service Advisor Shawn Gillespie
Technician Josiah Walker

Inspection

Arrival Inspection

Customer Concerns For This Visit:

Wheel Lock Key In Cup Holder: Yes/ No Wheel Lock Key/ Wheel Locks Need to be Extracted

Arrival Inspection

Sub \$0.00

-- Inspection Results from AutoVitals SmartFlow --

Arrival Inspection (internal only), rev. 1

<https://avlink.io/l/47Bqe41>

Oil Change Courtesy Inspection

Complementary visual inspection of common areas of concern or general maintenance. This is not a full mechanical inspection or safety inspection and as such may not identify all areas of concern, and does not indicate the vehicle safety.

Perform Inspection

\$0.00 G

Sub \$0.00

-- Inspection Results from AutoVitals SmartFlow --

VM Complimentary Oil Change Inspection, rev. 1

<https://avlink.io/l/47CZas1>

Service

Quality Control

Internal technician check over of vehicle before end of service to ensure quality control, and that repairs where done with the appropriate quality of workmanship, and all components are torqued, tight, and secured.

Inspection

\$0.00 G

Sub \$0.00

Lube, Oil & Filter Service - Full Synthetic Oil

Drain and refill engine oil, change engine oil filter and lubricate chassis grease fittings and friction points as required. Includes up to 6L of oil, oil required in excess of 6L will be an additional charge. Complete a complimentary visual vehicle inspection includes check and top off of under hood fluid levels, additional charges may apply where fluids are required.

Perform Service

\$40.00 G

Valvoline Full Synthetic 5W30

6 Unit

\$8.50 / Unit

\$51.00 EGH

Engine Oil Filter

1 Unit

\$18.00 / Unit

\$18.00 E2G

Sub \$109.00

-- Inspection Results from AutoVitals SmartFlow --

For 'Oil Change Due' the following conditions have been found: Oil Change Over Due By More Than 1,000 kms.

Notes:

Supporting Images and Videos:

* Image <https://avlink.io/l/47BqeJT>

For more info, check inspection results <https://avlink.io/l/47Bqe41>.

Total Parts	\$69.00
Total Labor	\$40.00
Total Before Taxes & Miscellaneous Charges	\$109.00

GST #736416470RT0001

(*) Shop Supplies		\$5.34 G
(E) Environmental Disposal	\$0.12 Each	\$0.72 G
(E2) Oil Filter Enviromental Fee	\$0.55 Each	\$0.55 G
(H) Hazardous Materials Disposal	\$0.55 Each	\$3.30 G
(G) Canadian Goods and Services Tax (GST)	5 %	\$5.95
Grand Total		\$124.86

Thank you for your business. PLEASE RETURN WITHIN 50 - 100 KM TO HAVE WHEELS RE-TORQUED. It is the customer's responsibility to return for re-torquing or have it done elsewhere. Failure to re-torque may result in wheel damage or loss, for which Venture Motorworks is not liable.

The work is complete, and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

This invoice reflects work authorized, including any applicable revisions to the original estimate authorized by the customer. Approvals for repairs were documented through digital inspection, phone, text, email, or in-person communication. Test drives were authorized by the customer as part of the service and quality control process.

Unless otherwise stated, all parts supplied are new aftermarket or OE-equivalent. Used parts, when supplied by Venture Motorworks, are noted on the invoice and include only a 30-day parts warranty unless otherwise stated. Customer-supplied parts are installed at the customer's risk and are not covered by any parts or labour warranty.

Most repairs performed by Venture Motorworks include a nationwide 2-year/40,000 km parts and labour warranty from the original date of service. Full terms and conditions are available at techauto.ca/warranty.

This repair also qualifies for nationwide roadside assistance. For service, call 1 (866) 588-0728. For full roadside assistance details, visit techauto.ca/roadside.

Removed parts have been recycled or discarded unless prior arrangements were made. Venture Motorworks is not responsible for personal belongings left in the vehicle.

We are not liable for loss or damage caused by theft, vandalism, fire, hail, or other acts of nature while the vehicle is on our premises. Full payment is due upon collection. Vehicles not picked up within 7 calendar days of job completion will incur a \$50/day storage fee starting on the 8th day.

I acknowledge the above and the indebtedness indicated herein.



Buyer agrees to pay total amount above according to cardholder's agreement with issuer.

Customer Signature: _____

Authorization(s)

9/23/2025 8:39 AM	\$124.86	In Person / Other
		Arrival Inspection
		Quality Control
		Lube, Oil & Filter Service - Full Synthetic Oil
		Authorized by Mcfarland, Payne



VENTURE MOTORWORKS

Venture Motorworks Limited
(403) 910-6259
info@venturemotorworks.ca
416 28 St NE, Calgary, AB, Canada,
T2A 6T3
Company Business/GST
number:736416470RT0001

Invoice # 208580
Against Estimate#: 12935
Created: Nov 20, 2024
Invoiced: Nov 21, 2024
Service Advisor: Shawn Gillespie

Deferred Service

Below are the services, **Payne Mcfarland** deferred to be completed in the future these services are not part of the invoice

Replace Rear Brake Pads and Rotors (3 mm)

Deferred

Service Notes: Brake: Disc/Disc/4-Wheel ABS

Item	Name	Description	Price	Qty/Hrs	Amount
1	Brake Pads and Rotors R&R (Rear, Brake: Disc/Disc/4-Wheel ABS)	Includes: The removal of component and all necessary components for access, and cleaning component. Does not include: Brake Hydraulic System Bleed. System diagnosis and testing, or a vehicle road test.	\$149.00	1.4	\$208.60
2	Akebono , PRO-ACT Ultra-Premium, Ceramic w/ Hardware Disc Brake Pad Set	ACT905A	\$141.01	1	\$141.01
3	Akebono , PRO-ACT Ultra-Premium, Zinc Coated Disc Brake Rotor	AK20116	\$109.45	2	\$218.90
					Service subtotal: \$568.51



VENTURE MOTORWORKS

Venture Motorworks Limited
(403) 910-6259
info@venturemotorworks.ca
416 28 St NE, Calgary, AB, Canada,
T2A 6T3
Company Business/GST
number:736416470RT0001

Invoice # 20515
Against Estimate#: 10947
Created: May 22, 2024
Invoiced: May 22, 2024
Service advisor: Israel Blanco

2015 Nissan Pathfinder
VIN: 5N1AR2MMXFC691401
Mileage: 123460 km

Motul Synthetic 0w20 Oil Change & Visual Inspection

Authorized

Service notes: Left Front Marker Light Is Out And Requires Replacement.

Rear Main Is Tarning To Sweat; Monitor For Now.

ItemName	Description	Price	QTY/HRS	Amount	
1	Engine Oil & Filter Change with Visual Inspection	Includes engine oil drain and refill up to 6L, filter change, and complimentary visual inspection. Oil required in excess of 6L is an additional charge.	\$40.00	1	\$40.00
2	Bosch , Workshop Engine Oil Filter	72230WS	\$14.03	1	\$14.03
3	Motul Synthetic 8100 ECO-LITE 0W20		\$8.40	6	\$50.40
4	Hazardous Materials Disposal Fee		\$0.55	6	\$3.30
5	Eco Fee	Alberta Recycling Management Authority Eco Fee as of 1 October 2023	\$0.12	6	\$0.72
6	Oil Filter Eco Fee	Alberta Recycling Management Authority Eco Fee as of October 1, 2023	\$0.55	1	\$0.55

Service subtotal: \$109.00

Quality Control Inspection

Authorized

ItemName	Description	Price	QTY/HRS	Amount
1	Quality Control Inspection			\$0.00

Service subtotal: \$0.00

Arrival Inspection

Authorized

ItemName	Description	Price	QTY/HRS	Amount
1	Arrival Inspection	Inspection of vehicle upon arrival		\$0.00

Service subtotal: \$0.00



VENTURE MOTORWORKS

Venture Motorworks Limited
(403) 910-6259
info@venturemotorworks.ca
416 28 St NE, Calgary, AB, Canada,
T2A 6T3
Company Business/GST
number:736416470RT0001

Invoice # 208580
Against Estimate#: 12935
Created: Nov 20, 2024
Invoiced: Nov 21, 2024
Service Advisor: Shawn Gillespie

2015 Nissan Pathfinder
VIN: 5N1AR2MMXFC691401
Mileage: 123456 km

Kuhmo All Season Tires

Authorized

Service Notes: Rear Brake Pads Are Low. Recommend Replacing Soon. Around 3mm On Them. Recommend Doing Brake Rotors As Well As They Are A Bit Rusty

Item	Name	Description	Price	Qty/Hrs	Amount
1	Mount & Balance 4 Tires - 19" Wheels & Under, 32" Tires & Under (Non-Low Profile or RFT)		\$150.00	0.8	\$120.00
2	Crugen HP71	2268173	\$174.88	4	\$699.52
3	Tire Levy		\$5.00	4	\$20.00

Service subtotal: \$839.52

Quality Control Inspection

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Quality Control Inspection				\$0.00

Service subtotal: \$0.00

Arrival Inspection

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Arrival Inspection	Inspection of vehicle upon arrival			\$0.00

Service subtotal: \$0.00



VENTURE MOTORWORKS

Venture Motorworks Limited

(403) 910-6259

info@venturemotorworks.ca

416 28 St NE, Calgary, AB, Canada,

T2A 6T3

Company Business/GST

number:736416470RT0001

Invoice # 208580

Against Estimate#: 12935

Created: Nov 20, 2024

Invoiced: Nov 21, 2024

Service Advisor: Shawn Gillespie

Date and Time	Receipt No	Payment Method	Amount
Nov 21, 2024 1:42 pm	11583		\$898.26

Service Amount	\$819.52
Part	\$0.00
Labor	\$120.00
Tire	\$699.52
Item Discount	\$24.00
Total Service Level Fee	
Tire Levy	\$20.00
Total RO Fees	
Shop supplies	\$39.96
Subtotal	\$855.48
Taxes	
GST (5%)	\$42.78
Grand total	\$898.26
Paid to date	\$898.26
Remaining Balance	\$0.00

By signing this document, you agree to the Terms and Conditions mentioned below.

Signature:

Disclaimer:

Thank you for your business. PLEASE RETURN WITHIN 100 KM TO HAVE WHEELS RETORQUED. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no parts or labour warranty provided for used parts or customer supplied parts.

Vehicles not collected within 7 calendar of work being completed will be charged a daily storage fee of \$50.



VENTURE MOTORWORKS

Venture Motorworks Limited
(403) 910-6259
info@venturemotorworks.ca
416 28 St NE, Calgary, AB, Canada,
T2A 6T3
Company Business/GST
number:736416470RT0001

Invoice # 208580
Against Estimate#: 12935
Created: Nov 20, 2024
Invoiced: Nov 21, 2024
Service Advisor: Shawn Gillespie

2015 Nissan Pathfinder
VIN: 5N1AR2MMXFC691401
Mileage: 123456 km

Kuhmo All Season Tires

Authorized

Service Notes: Rear Brake Pads Are Low. Recommend Replacing Soon. Around 3mm On Them. Recommend Doing Brake Rotors As Well As They Are A Bit Rusty

Item	Name	Description	Price	Qty/Hrs	Amount
1	Mount & Balance 4 Tires - 19" Wheels & Under, 32" Tires & Under (Non-Low Profile or RFT)		\$150.00	0.80	\$120.00
2	Crugen HP71	2268173	\$174.88	4.00	\$699.52
3	Tire Levy		\$5.00	4.00	\$20.00
			Amount:	Disc: -\$24.00	Subtotal:
			\$819.52	Fees: \$20.00	\$815.52

Quality Control Inspection

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Quality Control Inspection				\$0.00
			Amount:	Disc: \$-0.00	Subtotal:
			\$0.00		\$0.00

Arrival Inspection

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Arrival Inspection	Inspection of vehicle upon arrival			\$0.00
			Amount:	Disc: \$-0.00	Subtotal:
			\$0.00		\$0.00



VENTURE MOTORWORKS

Venture Motorworks Limited
(403) 910-6259
info@venturemotorworks.ca
416 28 St NE, Calgary, AB, Canada,
T2A 6T3
Company Business/GST
number:736416470RT0001

Invoice # 208580
Against Estimate#: 12935
Created: Nov 20, 2024
Invoiced: Nov 21, 2024
Service Advisor: Shawn Gillespie

Date and Time	Receipt No	Payment Method	Amount	Service Amount	
Nov 21, 2024 1:42 pm	11583	Card - Credit Card xxxx-xxxx-5327	\$898.26		
				Part	\$0.00
				Labor	\$120.00
				Tire	\$699.52
				Item Discount	- \$24.00
				Total Service Level Fee	
				Tire Levy	\$20.00
				Total RO Fees	
				Shop supplies	\$39.96
				Subtotal	\$855.48
				Taxes	
				GST (5%)	\$42.78
				Taxable:	\$855.48
				Non-Taxable:	\$0.00
				Grand total	\$898.26
				Paid to date	\$898.26
				Remaining Balance	\$0.00

By signing this document, you agree to the Terms and Conditions mentioned below.

Signature:

Disclaimer:

Thank you for your business. PLEASE RETURN WITHIN 100 KM TO HAVE WHEELS RETORQUED. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no parts or labour warranty provided for used parts or customer supplied parts.

Vehicles not collected within 7 calendar of work being completed will be charged a daily storage fee of \$50.



VENTURE MOTORWORKS

Venture Motorworks Limited
(403) 910-6259
info@venturemotorworks.ca
416 28 St NE, Calgary, AB, Canada,
T2A 6T3
Company Business/GST
number:736416470RT0001

Invoice # 20515
Against Estimate#: 10947
Created: May 22, 2024
Invoiced: May 22, 2024
Service advisor: Israel Blanco

Date and time	Receipt No	Payment method	Amount	Service Amount	
May 22, 2024 3:44 pm	10482	Card - Credit Card xxxx-xxxx- 5327	\$120.07		\$104.43
				Part	\$64.43
				Labor	\$40.00
				Total Service level fee	
				Hazardous Materials Disposal Fee	\$3.30
				Eco Fee	\$0.72
				Oil Filter Eco Fee	\$0.55
				Total RO Fees	
				Shop supplies	\$5.34
				Subtotal	\$114.34
				Passthrough Taxes	\$0.00
				Taxes	
				GST (5%)	\$5.73
				Grand total	\$120.07
				Paid to date	\$120.07
				Remaining balance	\$0.00

By signing this document, you agree to the Terms and Conditions mentioned below.

Signature: _____

Disclaimer:

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

CUSTOMER #: 142106

481171

CANYON CREEK



TOYOTA

370 Canyon Meadows Drive S.E.
Calgary, Alberta T2J 7C6
Service Direct: 403-225-5319
Phone: 403-278-6066
Fax: 403-278-6223
www.canyoncreektoyota.com
G.S.T. NO. 119406502

INVOICE

PAGE 1

SERVICE ADVISOR: 126942 PHILIP CHAN

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
BLACK	15	NISSAN Pathfinder		5N1AR2MMXFC691401		95727/95728		TMCFAR
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
08JUN21 DD			WAIT 13DEC21		149.00	CASH	13DEC21	
R.O. OPENED		READY		OPTIONS: STK:691401P ENG:3.5 LITER TRN:A				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A FREE OIL AND FILTER							
	01TOZ18	FREE OIL AND FILTER					
	120190IOILC						(N/C)
	GOGF	OIL FILTER RECYCLING FEE					(N/C)
	GOGR	RECYCLING FEE					(N/C)
	1	35934-PH6607	PH6607 FILTER				(N/C)
	5	COBBA-05W30-1L	GEN EO 5W-30 CASE				(N/C)
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	0.00
front tires 6/32 - 5/32, rear tires 6/32 - 6/32.							

Correctly supplied parts are subject to a 20% handling charge. "Customer acknowledges and confirms that he/she has declined TPMS, not withstanding Canyon Creek Toyota advice and suggestion that vehicle be equipped Customer understands and assures risk and waives any claim that he/she may have against Canyon Creek Toyota in that regard". "This dealership did not use the customer's lock lug nut key in any manner, as technician have their own master set to use." PRIVACY POLICY Canyon Creek Toyota collects, uses, and updates personal information with Toyota Canada for warranty and customer satisfaction purposes. Canyon Creek Toyota may communicate commercial electronic messages and offer promotions to busy, sell, trade or lease products and services to me. You may withdraw consent at any time, Wheels must be retorqued in 100KM New Toyota genuine parts installed by Canyon Creek Toyota and paid for by the Customer have a 24 month / 40,000 km warranty unless otherwise noted.	DESCRIPTION	TOTALS
	LABOR AMOUNT	0.00
	PARTS AMOUNT	0.00
	GAS, OIL, LUBE	0.00
	SUBLET AMOUNT	0.00
	MISC. CHARGES	0.00
	TOTAL CHARGES	0.00
	LESS INSURANCE	0.00
	G.S.T. TAX	0.00
	PLEASE PAY THIS AMOUNT	0.00

CANYON CREEK



TOYOTA

370 CANYON MEADOWS DRIVE S.E.

CALGARY, ALBERTA T2J 7C6

SERVICE DIRECT: 403-225-5319

PHONE: 403-278-6066

FAX: 403-278-6066

www.canyoncreektoyota.com

0101ITOIS463382

G.S.T. NO. 119406502

ALL ITEMS ARE SUBJECT TO G.S.T.

THE CUSTOMER IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE PARTS REQUIRED FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

CUSTOMER NO. 14108		ADVISOR LAWRENCE VIEGAS	TAG NO. 412 401U	INVOICE DATE 05/06/21	INVOICE NO. TOIS463382
LABOUR RATE 149.00		LICENSE NO.	KILOMETERS 85,344	COLOUR BLACK/	STOCK NO. 691401P
YEAR / MAKE / MODEL 15/NISSAN TRUCK/PATHFINDER/4DR 4WD S		DELIVERY DATE 85,350		DELIVERY KMS.	
VEHICLE I.D. NO. 5N1AR2MMXFC691401		SELLING DEALER NO.		PRODUCTION DATE	
R.T.E. NO.		P.O. NO.		R.O. DATE 03/23/21	
IN SERVICE DATE					
RESIDENCE PHONE	BUSINESS PHONE 403-278-6066	COMMENTS			
		MO: 85344			

MISC-----CODE-----	DESCRIPTION-----	CONTROL NO-----
JOB # A	ISS INTERNAL SHOP SUPPLIES	35.00
JOB # 2	CTSS DETAIL SHOP SUPPLIES	33.00
JOB # 2	REV REVERSE SS FOR MECH SHOP	-33.00
TOTAL - MISC		35.00

COMMENTS-----
AMVIC / CLEAN
85344/KM
FRONT BRAKES PADS AT 10MM
REAR BRAKES PADS AT 9MM
TIRES FRONT AND REAR AT 7/32
DRIVER DOOR MAKING NOISE WHEN CLOSE DOOR

TOTALS-----	
CONTROL# 691401P	ACCOUNT NUMBER AMOUNT..
TOTAL LABOR.... 1432.62	
TOTAL PARTS.... 1083.90	
TOTAL SUBLET... 360.51	
TOTAL G.O.G.... 5.08	
TOTAL MISC.CHG. 68.00	
TOTAL MISC.DISC -33.00	
TOTAL TAX..... 0.00	
TOTAL INVOICE \$ 2917.11	

APPROVED BY SIGNATURE _____

TOYOTA
QUALITY SERVICE

"We Care"

PARTS RETURN POLICY

Electrical parts or special order parts are **NON-RETURNABLE** and must be prepaid at time of order. All parts accepted for return must meet manufacturer's current packaging guidelines.

NO RETURN ON ITEMS UNDER \$10.00.

Correctly supplied parts are subject to a 20% handling charge.

"Customer acknowledges and confirms that he/she has declined TPMS, not withstanding Canyon Creek Toyota's advice and suggestion that vehicle be equipped. Customer understands and assumes risk and waives any claim that he/she may have against Canyon Creek Toyota in that regard."

"This dealership did not use the customer's lock lug nut key in any manner, as technicians have their own master set to use."

PRIVACY POLICY

Canyon Creek Toyota collects, uses, and updates personal information with Toyota Canada for warranty and customer satisfaction purposes. Canyon Creek Toyota may communicate commercial electronic messages and offer promotions to buy, sell, trade or lease products and services to me. You may withdraw consent at anytime.

Wheels must be retorqued in 100 KM

X

New Toyota genuine parts installed by Canyon Creek Toyota and paid for by the Customer have a 24 month / 40,000 km warranty unless otherwise noted.

Thank you for having your vehicle serviced at CANYON CREEK TOYOTA
Quotes/Estimates expire in 30 days.

Tell us about your experience!
Come find us on Facebook or Google Reviews.

Ask us about seasonal tire storage!

CANYON CREEK



TOYOTA

370 CANYON MEADOWS DRIVE S.E.

CALGARY, ALBERTA T2J 7C6

SERVICE DIRECT: 403-225-5319

PHONE: 403-278-6066

FAX: 403-278-6223

www.canyoncreektoyota.com 0101IT0IS463382

G.S.T. NO. 119406502

TOYOTA
GENUINE PARTS

ALL PARTS ARE SUBJECT TO G.S.T.
CUSTOMER IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE PARTS REQUIRED FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

CUSTOMER NO. 14108		ADVISOR LAWRENCE VIEGAS	TAG NO. 412 401U	INVOICE DATE 05/06/21	INVOICE NO. TOIS463382
LABOUR RATE 149.00		LICENSE NO.	KILOMETERS 85,344	COLOUR BLACK/	STOCK NO. 691401P
YEAR / MAKE / MODEL 15/NISSAN TRUCK/PATHFINDER/4DR 4WD S		DELIVERY DATE 03/23/21		DELIVERY KMS. 85,350	
VEHICLE I.D. NO. 5 N 1 A R 2 M M X F C 6 9 1 4 0 1		SELLING DEALER NO.		PRODUCTION DATE	
F.T.E. NO.		P.O. NO.		R.O. DATE 03/23/21	
IN SERVICE DATE					
RESIDENCE PHONE	BUSINESS PHONE 403-278-6066	COMMENTS			

MO: 85344

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 5	1	35934-1393CR	BRAKE PAD	59.99	
JOB # 5	2	35934-31348	REAR ROTOR	53.99	107.98
HERE					
JOB # 5 TOTAL PARTS					167.97
JOB # 5 TOTAL LABOR & PARTS					391.47

J# 6+18TOZZFR-09 FR. BRKS W/NEW ROTOR HOURS: 1.50 TECH(S):475 223.50

Added Operation (LAWRENCE @ 03/25/2021 09:45)

CONDITION: REPLACE FRONT BRAKES AND NEW ROTORS

CAUSE: FRONT BRAKES PADS AT 3MM

CORRECTION: REPLACED FRONT BRAKES PADS AND ROTORS

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 6	1	35934-1649CR	FRONT PADS	93.99	
JOB # 6	2	35934-44765	FRONT ROTOR	106.99	213.98
JOB # 6 TOTAL PARTS					307.97
JOB # 6 TOTAL LABOR & PARTS					531.47

J# 7+12TOZ ENG. HEATING/COOLING HOURS: 3.00 TECH(S):475 447.00

Added Operation (LAWRENCE @ 03/25/2021 09:45)

CONDITION: CAN THE THE FAN NOISE BE TIGHTENED

CAUSE: ----REPLACE FAN ----

CORRECTION: REPLACED RAD FAN,CHECK ALL TEMP CONTROL SWITCHES ARE WORKING AS DESIGN

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 7	1	C0EPP-2032C-05	BATTERY,TRANSM	4.15	
JOB # 7	1	38729-1334735	TYC FAN	563.53	563.53
JOB # 7 TOTAL PARTS					567.68
JOB # 7 TOTAL LABOR & PARTS					1014.68

J# 8+09TOZ MISCELLANEOUS HOURS: TECH(S):475 0.00

Added Operation (LAWRENCE @ 05/06/2021 10:40)

CONDITION: NEED TO TAKE TO NISSAN TO CHECK WHY AFTER RAD FAN REPLACED

SETTINGS ON DASH NOT WORKING

CAUSE: NO FAULT FOUND AT HOME DEALER FISHCREEK NISSAN

CORRECTION: NO FAULT FOUND

JOB # 8 TOTAL LABOR & PARTS 0.00

SUBLET	PO#	VEND INV#	INV DATE	DESCRIPTION	
JOB # 3	410607		03/26/21	WINDSHIELD	278.25
JOB # 8	410678		05/06/21	SUBLET CHECK	82.26
TOTAL - SUBLET					360.51

G.O.G. & SUPPLIES					
JOB # 4	1.0	OIL RECYCLING FEE	@	4.530	/UNIT 4.53
JOB # 4	1.0	OIL FILTER RECYCLING FEE	@	0.550	/UNIT 0.55
TOTAL - GOG					5.08

PARTS RETURN POLICY

Electrical parts or special order parts are NON-RETURNABLE and must be prepaid at time of order. All parts accepted for return must meet manufacturer's current packaging guidelines.

NO RETURN ON ITEMS UNDER \$10.00.

Correctly supplied parts are subject to a 20% handling charge.

"Customer acknowledges and confirms that he/she has declined TPMS, not withstanding Canyon Creek Toyota's advice and suggestion that vehicle be equipped. Customer understands and assumes risk and waives any claim that he/she may have against Canyon Creek Toyota in that regard."

"This dealership did not use the customer's lock lug nut key in any manner, as technicians have their own master set to use."

PRIVACY POLICY

Canyon Creek Toyota collects, uses, and updates personal information with Toyota Canada for warranty and customer satisfaction purposes. Canyon Creek Toyota may communicate commercial electronic messages and offer promotions to buy, sell, trade or lease products and services to me. You may withdraw consent at anytime.

Wheels must be retorqued in 100 KM

X

New Toyota genuine parts installed by Canyon Creek Toyota and paid for by the Customer have a 24 month / 40,000 km warranty unless otherwise noted.

Thank you for having your vehicle serviced at CANYON CREEK TOYOTA
Quotes/Estimates expire in 30 days.

Tell us about your experience!
Come find us on Facebook or Google Reviews.

Ask us about seasonal tire storage!

CANYON CREEK



370 CANYON MEADOWS DRIVE S.E.

CALGARY, ALBERTA T2J 7C6

SERVICE DIRECT: 403-225-5319

PHONE: 403-278-6066

FAX: 403-278-6066

www.canyoncreektoyota.com 0101ITOIS463382

G.S.T. NO. 119406502

TOYOTA
GENUINE PARTS

CUSTOMER NO. 14108		ADVISOR LAWRENCE VIEGAS	TAG NO. 412	INVOICE DATE 05/06/21	INVOICE NO. TOTS463382
RESIDENCE PHONE		LABOUR RATE 149.00	LICENSE NO.	COLOUR BLACK/	STOCK NO. 691401P
BUSINESS PHONE 403-278-6066		YEAR / MAKE / MODEL 15/NISSAN TRUCK/PATHFINDER/4DR 4WD S	KILOMETERS 85,344	DELIVERY DATE	DELIVERY KMS. 85,350
COMMENTS		VEHICLE I.D. NO. 5N1AR2MMXFC691401	P.O. NO.	SELLING DEALER NO.	PRODUCTION DATE
		F.T.E. NO.		R.O. DATE 03/23/21	IN SERVICE DATE

LABOR & PARTS				
J# 1 70TOZZ01	MECHANICAL FITNESS	HOURS: 1.00	TECH(S): 475	
CONDITION: MECHANICAL FITNESS INSPECTION				
INCLUDES REMOVAL OF LICENSE PLATE SCREWS				
FORMS FILLED OUT				
CAUSE: TEST BLOCK HEATER OPERATION				
CORRECTION: COMPLETED USED VEHICLE INSPECTION				
JOB # 1 TOTAL LABOR & PARTS			149.00	
J# 2 74TOZUC-B	ULTIMATE VANTRUCKSUV	HOURS: 4.50	TECH(S): 134645	
CONDITION: ULTIMATE CLEAN OF EITHER TRUCK/SUV/VAN				
\$329.95 PLUS SUPPLIES				
CAUSE: AS REQUESTED				
CORRECTION: COMPLETED ULTIMATE CLEAN				
JOB # 2 TOTAL LABOR & PARTS			329.95	
J# 3 80TOZZ01	ECO GLASS/OEM GLASS	HOURS: 0.00	TECH(S): 475	
Added Operation (LAWRENCE @ 03/25/2021 09:45)				
CONDITION: INSTALL OF AFTERMARKET OR OEM WINDSHIELDS ON VEHICLES 2016				
AND UP EQUIPPED WITH PCS SYSTEM OR ANY FORWARD FACING CAMERA				
MUST BE CALIBRATED AFTER WINDSHIELD IS REPLACED.				
AN ADDITIONAL 1.5 HRS REQUIRED TO HAVE CALIBRATION OF PCS				
IF EQUIPPED REFER AND ADD LABOR OP 78 CALIBRATE WINDSHIELD				
PERFORMED BY TRAINED TECH AT 148.88/HOUR				
CAUSE: CRACKED				
CORRECTION: REPLACED WINDSHIELD				
JOB # 3 TOTAL LABOR & PARTS			0.00	
J# 4 01TOZPREMIUM	PREMIUM OIL CHANGE	HOURS: 0.00	TECH(S): 475	
Added Operation (LAWRENCE @ 03/25/2021 09:45)				
CONDITION: PERFORM PREMIUM OIL AND FILTER SERVICE.				
CAUSE: MAINTENANCE				
CORRECTION: PERFORMED OIL CHANGE, INSPECTED FLUID LEVELS, TOPPED UP				
LEVELS, SET TIRE PRESSURE, LUBRICATED LATCHES AND HINGES.				
SEE ATTACHED DETAILED INSPECTION REPORT.				
PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
JOB # 4	1	35934-PH6607	PH6607 FILTER	11.99
JOB # 4	1	90430-12031	GASKET	1.39
JOB # 4	5	COBBA-05W30-1L	GEN EO 5W-30 C	5.38
JOB # 4 TOTAL PARTS			40.28	
JOB # 4 TOTAL LABOR & PARTS			99.95	
J# 5 18TOZZER-10	REAR BRK W/NEW R/D	HOURS: 1.50	TECH(S): 475	
Added Operation (LAWRENCE @ 03/25/2021 09:45)				
CONDITION: REPLACE REAR BRAKES AND NEW ROTORS				
CAUSE: REAR BRAKES PADS AT 1MM				
CORRECTION: REPLACED REAR BRAKES PADS AND ROTORS				

PARTS RETURN POLICY

Electrical parts or special order parts are **NON-RETURNABLE** and must be prepaid at time of order. All parts accepted for return must meet manufacturer's current packaging guidelines.

NO RETURN ON ITEMS UNDER \$10.00.

Correctly supplied parts are subject to a 20% handling charge.

"Customer acknowledges and confirms that he/she has declined TPMS, not withstanding Canyon Creek Toyota's advice and suggestion that vehicle be equipped. Customer understands and assumes risk and waives any claim that he/she may have against Canyon Creek Toyota in that regard."

"This dealership did not use the customer's lock lug nut key in any manner, as technicians have their own master set to use."

PRIVACY POLICY

Canyon Creek Toyota collects, uses, and updates personal information with Toyota Canada for warranty and customer satisfaction purposes. Canyon Creek Toyota may communicate commercial electronic messages and offer promotions to buy, sell, trade or lease products and services to me. You may withdraw consent at anytime.

Wheels must be retorqued in 100 KM

X

New Toyota genuine parts installed by Canyon Creek Toyota and paid for by the Customer have a 24 month / 40,000 km warranty unless otherwise noted.

Thank you for having your vehicle serviced at CANYON CREEK TOYOTA

Quotes/Estimates expire in 30 days.

Tell us about your experience!

Come find us on Facebook or Google Reviews.

Ask us about seasonal tire storage!