

Don't Panic Mechanic LTD.

225 Railway St East
Cochrane, AB. T4C2C3
Phone: 403-797-7534

INVOICE**4304**

Org. Est. # 004632
GST#700895717RT001

Date: 04/22/2024

2011 Toyota - Sienna LE - 3.5L, V6 (211CI) VIN(K)

Lic # :

Odometer In : 0

Odometer Out : 284132

VIN # : 5TDKK3DC9 BS157471

Part Description	Qty	Sale	Ext	Labor Description	Ext
BRAKE PADS	1.00	189.78	189.78	REPLACE FRONT & REAR BRAKE PADS.	390.00
BRAKE ROTOR	2.00	150.11	300.22	SERVICE FRONT & REAR CALIPERS, BRACKETS & PINS	
BRAKE CLEAN	2.00	17.76	35.52	[Discount] \$65.00 off parts	
BRAKE PADS	1.00	101.53	101.53		
BRAKE ROTOR	2.00	96.38	192.76		
Shop Supplies			27.30		
Hazardous Materials			12.00		

Org. Estimate 1,243.32 Revisions 0.00 Current Estimate 1,243.32

Labor:	390.00
Parts:	847.11
HazMat:	12.00
Discount:	-65.00
SubTotal:	1,184.11
Tax:	59.21
Total:	1,243.32
Bal Due:	\$1,243.32

[Payments -]

Vehicle Received: 4/22/2024

Customer Number : 2215

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection.


NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

HAVE WHEELS RE-TORQUED 100KM AFTER ALL REPAIRS TO BRAKES, SUSPENSION OR INSPECTIONS OF YOUR VEHICLE

Signature _____ Date _____

Visit us on the web : www.dontpanicmechanic.com

Our Email Address: dontpanicmechanicltd@gmail.com

**Don't Panic Mechanic LTD.**

225 Railway St East
Cochrane, AB. T4C2C3
Phone: 403-797-7534

INVOICE**5640**

GST#700895717RT001

INVOICE

Printed Date: 05/06/2025

Work Completed: 05/06/2025

2011 Toyota - Sienna LE - 3.5L, V6 (211CI) VIN(K)

Lic # :

Odometer In : 0

Odometer Out : 303838

VIN # : 5TDKK3DC9 BS157471

Part Description	Qty	Sale	Ext	Labor Description	Ext
LOWER CONTROL ARM SET	1.00	688.88	688.88	LOWER CONTROL ARMS	
Shop Supplies			42.00	CHECK LOWER CONTROL ARMS	600.00
Hazardous Materials			12.00	REPLACE BOTH LOWER CONTROL ARMS	

Org. Estimate 1,410.02 Revisions 0.00 Current Estimate 1,410.02

Labor:	600.00
Parts:	730.88
HazMat:	12.00
SubTotal:	1,342.88
Tax:	67.14
Total:	1,410.02
Bal Due:	\$1,410.02

[Payments -]

Vehicle Received: 2025-05-06

Customer Number : 2215

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection.
NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

HAVE WHEELS RE-TORQUED 100KM AFTER ALL REPAIRS TO BRAKES, SUSPENSION OR INSPECTIONS OF YOUR VEHICLE

Signature _____ Date _____

Visit us on the web: www.dontpanicmechanic.comEmail Address: dontpanicmechanicltd@gmail.com

COCHRANE

8 RIVER HEIGHTS DRIVE
COCHRANE, AB
T4C 0N8

PH: (403) 851-2920
FAX: (403) 851-2929
www.cochranetoyota.com
service@cochranetoyota.com
GST No. 821129210 RT

SO# 354464

Status

Printed: 03/11/2024 1:56:04 PM

SERVICE ORDER CUSTOMER COPY

User



LUCASP

Page 1

Advisor	Lucas Pretty	Promised	03/11/2024 5:30 PM	Tag#	1301
Shop	T1	Opened	03/11/2024 8:14 AM	Location	
Priority		Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
TAM123	282936	282936	09/13/2011	
Year Make	Model	Model Number	Colour	
2011 TOYOTA	SIENNA	KK3DCT	0040 Super	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
5TDKK3DC9BS157471	14094		08/10/2011	
Engine	3.5L DOHC 24-valve VVT-i V6 engine	Freezer number		

Labour	Description	Job	CSR	Status	Amount
01TOZZ-	Oil & Filter Service - 0w20 Synthetic \$106.70 Engine Air Filter Yes/No Wiper Blads Yes/No	1	LUCASP	Original	34.95

Part	Description	Shp	Bin	Retail	Price	Amount
PK7A1020	OIL CHANGE KIT	1			61.80	61.80
90430-12031	GASKET	1	38E01		0.00	0.00
04152-YZZA1	REPLACEABLE ELEMENT	1	35C01		0.00	0.00
E50	FILTER ENVIRO FEE	1	ENVIRO	0.55	0.55	0.55
C0BBA-0W2SN-0B	0W20 GF5	7	BULK1		0.00	0.00
E10	OIL & CONTAINER FEE	7	ENVIRO	0.18	0.18	1.26

Technician	JAXONV -	Parts Total	63.61
Cause	Replace engine oil & filter. Remove & inspect air filter element (replace when required). Lubricate locks, latches & hinges. Inspect lights, horn & wipers for proper function. Inspect coolant, brake & washer fluid levels. Inspect tires & adjust pressure as required, including spare.	Labour Total	34.95
Correction	Completed Oil and Filter Service. Please see Vehicle Inspection Report.	Request Sub-total	98.56

Labour	Description	Job	CSR	Status	Amount
02TOZO	Perform a Complimentary Quick Check Wheel Alignment Inspection. \$134.95 if Adjustments are required Yes / No (Please add additional line)	2	LUCASP	Original	0.00
Technician	MELPBS -				
Cause	Completed Wheel Alignment Inspection.				
Correction	Wheel Alignment In/Out				

Labour	Description	Job	CSR	Status	Amount
18TOZO-007	Replace Brake Fluid as per regular Maintenance \$212.44 Every 48,000 KM	3	LUCASP	Original	170.00

Part	Description	Shp	Bin	Retail	Price	Amount
------	-------------	-----	-----	--------	-------	--------

We have pre-booked your next service appointment

for ____ / ____ / ____

we will contact you two weeks prior to confirm.

Book your next detail service @



Thank You
for your
business

COCHRANE

8 RIVER HEIGHTS DRIVE
COCHRANE, AB
T4C 0N8

PH: (403) 851-2920
FAX: (403) 851-2929
www.cochranetoyota.com
service@cochranetoyota.com
GST No. 821129210 RT

SO# 354464

Status

Printed 03/11/2024 1:56:24 PM

SERVICE ORDER CUSTOMER COPY

User



LUCASP

Page 2

Advisor	Lucas Pretty	Promised	03/11/2024 5:30 PM	Tag#	1301
Shop	T1	Opened	03/11/2024 8:14 AM	Location	
Priority		Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
TAM123	282936	282936	09/13/2011	
Year	Make	Model	Model Number	Colour
2011	TOYOTA	SIENNA	KK3DCT	0040 Super
Vehicle ID No	Selling Dealer	Extended Warranty		Delivery Date
5TDKK3DC9BS157471	14094			08/10/2011
Engine	3.5L DOHC 24-valve VVT-i V6 engine	Engine Number		

PK2BF	BRAKE FLUID	1		15.95	15.95
C0009-00127	DOT 3 BRAKE FLUID 47	2	41C02	0.00	0.00
Technician	9022 -		Parts Total		15.95
Cause	Brake fluid is recommended to be replaced every 2 years or 48,000 KM.		Labour Total		170.00
Correction	Drained and filled brake fluid. Bled air from the system and adjusted the brake fluid level. Road tested vehicle for proper brake operation.		Request Sub-total		185.95

Labour	Description	Job	CSR	Status	Amount
05TOZ0-002	CHECK CONDITION OF COOLANT. RECOMMEND IF DUE FOR REPLACEMENT	4	LUCASP	Original	0.00
Technician	MELPBS -				
Correction					

Labour	Description	Job	CSR	Status	Amount	
09TOZA0-00	REPLACE ENGINE AIR FILTER	5	LUCASP	Approved	0.00	
Part	Description	Shp	Bin	Retail	Price	Amount
17801-0P051	ELEMENT SUB-ASSEMBLY	1	40D05	39.50	39.50	39.50
Technician	JAXONV -		Parts Total			39.50
Cause	ENGINE AIR FILTER IS CONTAMINATED		Request Sub-total			39.50
Correction	INSTALLED NEW ENGINE AIR FILTER					

SHUTTLE Web created 2024-03-09 06:44:16pm taken by JODY SZKORUPA

Labour	204.95
Parts	119.06
Supplies	21.52
Sub-Total	345.53
GST	17.28
Total Invoice	362.81

We have pre-booked your next service appointment

for ____ / ____ / ____,


we will contact you two weeks prior to confirm.

Book your next detail service @



Thank You
for your
business

COCHRANE




TOYOTA

Cochrane Toyota

∞xtime

Automobile Status Report

Prepared For



2011 Toyota SIENNA

Date March 11, 2024

VIN 5TDKK3DC9BS157471

Mileage 282936

RO# 354464

Service Advisor

Lucas Pretty

lppretty@cochranetoyota.com

4038512918

COCHRANE



TOYOTA

Cochrane Toyota
8 River Heights Drive
Calgary, AB T4C 2C5

Repair Estimate

Service Advisor
Lucas Pretty (LUCASP)
lpretty@cochranetoyota.com
4038512918

Date 03/11/2024 01:56 PM
2011 Toyota SIENNA
VIN 5TDKK3DC9BS157471
Mileage 282,936
RO# 354464

Service Name Approved	Price
[Primary]: 01TOZZ-LOF6T-0W : Oil & Filter Service - 0w20 Synthetic \$106.70 Engine Air Filter Yes/No Wiper Blads Yes/No	\$154.11
[Primary]: 18TOZ0-007 : Replace Brake Fluid as per regular Maintenance \$212.44 Every 48,000 KM	\$185.95
Printed on March 11, 2024	
Quote expires on April 10, 2024	

Subtotal	\$340.06
Shop Charges	\$23.21
Tax	\$18.16
Total	\$381.42


COCHRANE



Cochrane Toyota
8 River Heights Drive
Calgary, AB T4C 2C5

(403) 932-9900


COCHRANE



Cochrane Toyota

∞xtime Automobile Status Report

Prepared For



2011 Toyota SIENNA

Date August 19, 2026

VIN 5TDKK3DC9BS157471

Mileage 330326

RO# 397284

Service Advisor

Damian Lexington

dlexington@cochranetoyota.com

COCHRANE



Cochrane Toyota
8 River Heights Drive
Calgary, AB T4C 2C5

Additional Service Recommendations

In the process of inspecting your vehicle for safety and reliability, your technician Zachary P made the following observations and recommends that you do the necessary repairs to resolve these issues.

■ Red: requires immediate attention.

Yellow: in need of attention soon.


Tire Rotation: Recommend rotating tires due to better tread on the rear and front wheel drive

Item Description

Tire rotation helps protect tires against uneven wear by moving the tire location on the vehicle. Most tires will exhibit some form of wear based on numerous factors including: wheel alignment, miles driven, driving style and habits, and tire location on the vehicle. By moving or "rotating" the tires as recommended by the vehicle manufacturer, tires may wear more evenly; helping extend the life of the tires.

Reason

If not done, you will experience vibration in the steering wheel at certain highway speeds. Also, vibration will occur in the seat or floorboard at certain highway speeds. Tire wear will become scalloped or cupped.




Tires

[Other]: Recommend replacing passenger side rear door power sliding door cable due to broken

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



Windshield Wiper Blade

**Wiper Blade Replacement - Inserts:
Recommend replacing rear wiper
insert due to streaking on window**

Item Description

The wiper blade insert is a rubber blade attached to the end of the wiper arm.

Reason

If not replaced, worn out wiper blades can cause restricted visibility and permanent damage to the windshield.

Repair Estimate

PREPARED FOR
Jody Szkorupa
(403) 200-3157

Service Advisor
Damian Lexington (DAMIANL)
dlexington@cochranetoyota.com

Date 08/19/2026 02:47 PM
2011 Toyota SIENNA
VIN 5TDKK3DC9BS157471
Mileage 330,326
RO# 397284

Service Name Approved	Price
[Primary]: 01TOZZ-LOF6T-0W : Oil & Filter Service - 0w20 Synthetic Engine Air Filter Yes/No \$45.00 Wiper Blades Yes/No \$160.88	\$188.84
[Primary]: 01TO1A003 : HOF - Perform Toyota Engine Oil system Cleaning Service Recommended if the oil and filter service is more than 3,000 km past due, the vehicle is subjected to heavy duty service, or as suggested preventative maintenance every 48,000 km. (MUST BE USED IN CONJUNCTION WITH AN OIL CHANGE SERVICE) \$95.49	\$87.55
[Primary]: 05TOZ0-010 : C/S: DEFERRED MAINTENANCE SERVICE	\$0.00
[Primary]: 02TOZ0 : Perform a Complimentary Quick Check Wheel Alignment Inspection. (If applicable) Adjustments are required Yes / No (Please add additional line)	\$0.00
[Primary]: 74TOZZ01B : 7-11 Soft Touch Cloth Wash - Please supply a voucher for a luxury car wash and a complimentary medium coffee or slurpee. Voucher to be redeemed only at the 7-11 on River Heights Drive Retail value \$23.00 ***Please note: this is a soft-touch cloth car wash***	\$0.00
[Primary]: 05TOZ0-VIDEO : As part of your service today, your technician will provide a personalized video of your vehicle, highlighting its condition and any findings.	\$0.00
Printed on August 19, 2026	
Quote expires on September 18, 2026	

Subtotal	\$276.39
Shop Charges	\$30.76
Tax	\$15.36
Total	\$322.51

Service Name Undecided	Price
Wiper Blade Replacement - Front: Recommend replacing both front wiper blades due to drivers streaking and passenger side has no rubber left on it	\$68.86
Wiper Blade Replacement - Inserts: Recommend replacing rear wiper insert due to streaking on window	\$36.38
Tire Rotation: Recommend rotating tires due to better tread on the rear and front wheel drive	\$92.76
[Other]: Recommend replacing passenger side rear door power sliding door cable due to broken	\$641.72
Printed on August 19, 2026	
Quote expires on September 18, 2026	

Subtotal	\$839.72
Shop Charges	\$65.00
Tax	\$45.24
Total	\$949.96

COCHRANE



Cochrane Toyota
8 River Heights Drive
Calgary, AB T4C 2C5

(403) 932-9900



**COCHRANE
TOYOTA**

8 RIVER HEIGHTS DRIVE
COCHRANE, AB
T4C 0N8

PH: (403) 851-2920
FAX: (403) 851-2929
www.cochranetoyota.com
service@cochranetoyota.com
GST No. 821129210 RT

SO # 397284

Status WAITING
Printed 08/19/2026 2:53:20 PM

SERVICE ORDER CUSTOMER COPY



User DAMIL Page 1

Advisor	Damilan Levinson	Promised	08/19/2026 2:30 PM	Tag#	4009
Shop	T1	Opened	08/19/2026 1:03 PM	Location	
Priority		Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
TAM123	330326	330328	09/13/2011	
Year	Make	Model	Model Number	Colour
2011	TOYOTA	SIENNA	KK3DCT	0040 Super
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
5TDKK3DC9BS157471	14094		08/10/2011	
Engine	3.5L DOHC 24-valve VVT-i V6 engine	Fleet #		

Labour	Description	Job	CSR	Status	Amount
01TOZZ-	Oil & Filter Service - 0w20 Synthetic Engine Air Filter Yes/No Wiper Blades Yes/No	1	DAMIL	Original	56.66

Part	Description	Shp	Retail	Price	Amount
PK7A1020	OIL CHANGE KIT	1		84.80	84.80
90430-12031	GASKET	1		0.00	0.00
04152-YZZA1	REPLACEABLE ELEMENT	1		0.00	0.00
E50	AB GOV EHC FEE	1	0.55	0.55	0.55
C0BBA-0W2SN-0B	0W20 GF5	6		0.00	0.00
E10	AB GOV EHC FEE	6	0.18	0.18	1.08
17801-0P051	ELEMENT SUB-ASSEMBLY	1	45.75	45.75	45.75

Technician	ZACHP -	Parts Total	132.18
Cause	Replace engine oil & filter. Remove & inspect air filter element (replace when required). Lubricate locks, latches & hinges. Inspect lights, horn & wipers for proper function. Inspect coolant, brake & washer fluid levels. Inspect tires & adjust pressure as required, including spare.	Labour Total	56.66
Correction	Completed Oil and Filter Service. Please see Vehicle Inspection Report.	Request Sub-total	188.84

Lubricated all hinges and latches
Topped up washer fluid
Checked all other fluid levels are good
Replaced engine air filter
Adjusted tire pressure
Placed maintenance reminder sticker in window

Labour	Description	Job	CSR	Status	Amount
01TO1A003	HOF - Perform Toyota Engine Oil system Cleaning Service Recommended if the oil and filter service is more than 3,000 km past due, the vehicle is subjected to heavy duty service, or as suggested preventative maintenance every 48,000 km. (MUST BE USED IN CONJUNCTION WITH AN OIL CHANGE SERVICE)	2	DAMIL	Original	63.00

We have pre-booked your next service appointment

for ____ / ____ / ____,

we will contact you two weeks prior to confirm.

Book your next detail service @



*Thank You
for your
business*



**COCHRANE
TOYOTA**

8 RIVER HEIGHTS DRIVE
COCHRANE, AB
T4C 0N8

PH: (403) 851-2920
FAX: (403) 851-2929
www.cochranetoyota.com
service@cochranetoyota.com
GST No. 821129210 RT

SO # 397284

Status WAITING
Printed 08/19/2026 2:53:20 PM

SERVICE ORDER CUSTOMER COPY



User DAMIL Page 2

Advisor	Damil Levinson	Promised	08/19/2026 2:30 PM	Tag#	4009
Shop	T1	Opened	08/19/2026 1:03 PM	Location	
Priority		Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
TAM123	330326	330328	09/13/2011	
Year	Make	Model	Model Number	Colour
2011	TOYOTA	SIENNA	KK3DCT	0040 Super
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
5TDKK3DC9BS157471	14094		08/10/2011	
Engine	3.5L DOHC 24-valve VVT-i V6 engine	Fleet #		

Part	Description	Shp	Retail	Price	Amount
G0009-31100	ENGINE OIL CLEANER	1	24.22	24.22	24.22
E33	AB GOV EHC FEE	1	0.33	0.33	0.33
Technician	ZACHP -	Parts Total			24.55
Cause	Prior to oil change, with the engine warm, poured the contents of one bottle into the engine oil crankcase. Then ran the engine at idle for 15 minutes.	Labour Total			63.00
Correction	Completed Toyota Engine Oil System Cleaning Service	Request Sub-total			87.55

Labour	Description	Job	CSR	Status	Amount
05TOZ0-010	C/S: DEFERRED MAINTENANCE SERVICE	3	DAMIL	Original	0.00
Cause	Following Toyota's recommended maintenance ensures proper operation of all vehicle systems and helps prevent unforeseen repairs.				
Correction	Please see Toyota Maintenance guide for recommended maintenance.				

Labour	Description	Job	CSR	Status	Amount
02TOZ0	Perform a Complimentary Quick Check Wheel Alignment Inspection. (If applicable) Adjustments are required Yes / No (Please add additional line)	4	DAMIL	Original	0.00
Technician	HOUSE TECH -				
Cause	Completed Wheel Alignment Inspection.				
Correction	Adjustments are required Yes / No Customer authorizes alignment Yes / No (please add additional line)				

Labour	Description	Job	CSR	Status	Amount
74TOZZ01B	7-11 Soft Touch Cloth Wash - Please supply a voucher for a luxury car wash and a complimentary medium coffee or slurpee. Voucher to be redeemed only at the 7-11 on River Heights Drive Retail value \$23.00 ***Please note: this is a soft-touch cloth car wash***	5	DAMIL	Original	0.00

We have pre-booked your next service appointment


for ____ / ____ / ____,

we will contact you two weeks prior to confirm.

Book your next detail service @



*Thank You
for your
business*



**COCHRANE
TOYOTA**

8 RIVER HEIGHTS DRIVE
COCHRANE, AB
T4C 0N8

PH: (403) 851-2920
FAX: (403) 851-2929
www.cochranetoyota.com
service@cochranetoyota.com
GST No. 821129210 RT

SO # 397284

Status WAITING

**SERVICE ORDER
CUSTOMER COPY**



User

DAMIL

Page 3

Advisor	Damilan Levinson	Promised	08/19/2026 2:30 PM	Tag#	4009
Shop	T1	Opened	08/19/2026 1:03 PM	Location	
Priority		Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
TAM123	330326	330328	09/13/2011	
Year	Make	Model	Model Number	Colour
2011	TOYOTA	SIENNA	KK3DCT	0040 Super
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
5TDKK3DC9BS157471	14094		08/10/2011	
Engine	3.5L DOHC 24-valve VVT-i V6 engine	Fleet #		

Technician HOUSE TECH -
Cause Voucher is valid for 30 days from the invoice date.
Correction Enjoy your soft touch car wash & beverage compliments of Cochrane Toyota!

Labour	Description	Job	CSR	Status	Amount
05TOZ0-	As part of your service today, your technician will provide a personalized video of your vehicle, highlighting its condition and any findings.	6	DAMIL	Original	0.00
Technician	HOUSE TECH -				
Cause	Recorded and uploaded personalized vehicle video highlighting condition and recommendations.				
Correction	Video Inspection / Green report sent to Customer				

WAIT BDC created 2026-08-17 09:16:00am taken by Jonathan Pinter \$256.37 QUOTED
NEED TO QUOTE SLIDING DOOR REPAIR. SEE WEP39 FOR DETAILS. WILL NEED
DIAGNOSIS TO START AND THEN QUOTE OUT REPAIR, IF APPLICABLE. 230PM
FINISH TIME

Labour	119.66
Parts	156.73
Fees	0.00
Supplies	14.36
Sub-Total	290.75
GST	14.54
Total Invoice	305.29

We have pre-booked your next service appointment

for ____ / ____ / ____,

we will contact you two weeks prior to confirm.

Book your next detail service @



*Thank You
for your
business*