

CUSTOMER #: 16395
 UNIT# 10012117

283723



DEERFOOT - CORNER OF HERITAGE
 46 HERITAGE MEADOWS RD. SE
 CALGARY, ALBERTA T2H 3C1
 TELEPHONE: (403) 258-2255 FAX: (403) 258-2418
 www.hyattinfiniti.com

INVOICE

PAGE 1

SERVICE ADVISOR: 615 ROBERT OBRONT

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG	
BLACK	08	INFINITI FX35	JNRAS08W08X208048	JNE267	245285/245288	T1190	
IN SERVICE DATE	DEL DATE	WARR EXP	PROMISED	PO NO	RATE	PAYMENT	INV DATE
14FEB08 IS			15:00 04MAY26		0.00	CASH	04MAY26
14FEB08 DD							
R.O. OPENED	READY	OPTIONS: STK:I10012117					
04MAY26	04MAY26						

LINE	OPCODE	TECH	TYPE	HOURS	RETAIL	NET	TOTAL
A	C/S:	SEASONAL TIRE STORAGE - 1 SEASON (6 MONTHS)					
		STO SEASONAL TIRE STORAGE - 1 SEASON (6 MONTHS)					
		352 C				0.00	0.00
		1 STORAGE TIRE/STORAGE			140.00	140.00	140.00
PARTS:		140.00 LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	140.00

B	C/S:	SEASONAL TIRE SWAP (OFF RIMS) - INCLUDES MOUNT & BALANCE					
		122 SEASONAL TIRE SWAP (OFF RIMS) - INCLUDES MOUNT & BALANCE					
		352 C				229.95	229.95
PARTS:		0.00 LABOR:	229.95	OTHER:	0.00	TOTAL LINE B:	229.95
		245285 MOUNTED AND BALANCED 4 SUMMER TIRES, WINTER TIRES SENT TO STORAGE. TIRES PRESSURES ADJUSTED, LUG NUTS HAND TORQUE					

C	C/S:	REPLACE ENGINE OIL AND FILTER					
		OC REPLACE ENGINE OIL AND FILTER					
		352 C				73.98	73.98
		1 15208-65FOE FILTER, OIL			19.36	19.36	19.36
		1 11026-JA00A DRAIN GASKET			2.43	2.43	2.43
		1 EHC ENVIRO CHARGE			0.75	0.75	0.75
		5 99998-E120809 MS3000 5W30 BL			9.16	9.16	45.80
		5 EHC10 ENVIRO FEE			0.15	0.15	0.75
PARTS:		69.09 LABOR:	73.98	OTHER:	0.00	TOTAL LINE C:	143.07
		245285 Complete oil and filter change service with basic multi-point inspection					

D	C/S:	REPLACE BRAKE FLUID					
		602 REPLACE BRAKE FLUID					
		352 C				227.00	227.00
		1 84032 BRAKE FLUID			47.95	47.95	47.95
		1 EHC10 ENVIRO FEE			0.15	0.15	0.15

"At Your Service"
 Monday to Friday
 7:00 am - 6:00 pm
 Saturday by appointment

SERVICE
 258-2255

*Thank you
 for
 allowing us to
 service
 your vehicle*

DESCRIPTION	
LABOUR AMOUNT	
PARTS AMOUNT	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
INSURANCE/PAYABLE	
G.S.T.	
PAY THIS AMOUNT	

GST # 828512772.RT0001

We and our service providers and affiliates will use the information provided by you to (i) perform services as may be directly requested by you; (ii) provide more information regarding the products and services of us, our affiliates and business partners. (iii) Generate statistical and aggregated data that does not identify you personally, and (iv) disclose your information to our service providers and affiliates for the purpose of providing services to you and to provide you more information regarding their products and services. By providing your information to us, you consent to these uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.

CUSTOMER COPY



CUSTOMER #: 16395
 UNIT# 10012117

283723



**HYATT
INFINITI**

DEERFOOT - CORNER OF HERITAGE
 46 HERITAGE MEADOWS RD. SE
 CALGARY, ALBERTA T2H 3C1
 TELEPHONE: (403) 258-2255 FAX: (403) 258-2458
 www.hyattinfiniti.com

INVOICE

PAGE 2

SERVICE ADVISOR: 615 ROBERT OBRONT

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG	
BLACK	08	INFINITI FX35	JNRAS08W08X208048	JNE267	245285/245288	T1190	
IN SERVICE DATE	DEL DATE	WARR EXP	PROMISED	PO NO	RATE	PAYMENT	INV DATE
14FEB08 IS							
14FEB08 DD			15:00 04MAY26		0.00	CASH	04MAY26
R.D. OPENED	READY	OPTIONS: STK:T10012117					
04MAY26	04MAY26						

LINE	OPCODE	TECH	TYPE	HOURS	RETAIL	NET	TOTAL	
PARTS:				48.10	LABOR:	227.00	OTHER: 0.00	TOTAL LINE D: 275.10
245285 COMPLETED BRAKE FLUID FLUSH				*****				
E D/S : *CABIN AIR FILTER REPLACEMENT C/S: C/S: A/C CABIN FILTER - REPLACE								
307 A/C CABIN FILTER - REPLACE				352	C	99.95	99.95	
1 27277-VP01A FILTER				55.49		55.49	55.49	
PARTS:				55.49	LABOR:	99.95	OTHER: 0.00	TOTAL LINE E: 155.44
245285 REPLACED CABIN AIR FILTER ASSEMBLY				*****				
F D/S : *ENGINE AIR FILTER REPLACEMENT C/S: C/S: REPLACE ENGINE AIR FILTER								
202 REPLACE ENGINE AIR FILTER				352	C	9.95	9.95	
1 16546-0Z000 FILTER, AIR				55.39		55.39	55.39	
PARTS:				55.39	LABOR:	9.95	OTHER: 0.00	TOTAL LINE F: 65.34
245285 AIR FILTER REPLACED.				*****				
G MULTI POINT INSPECTION								
MPI IF YOUR WHEELS WERE REMOVED ON YOUR SERVICE TODAY - PLEASE RETURN TO THE DEALERSHIP IN 100KMS FOR A WHEEL RE-TORQUE.								
PARTS:				0.00	LABOR:	0.00	OTHER: 0.00	TOTAL LINE G: 0.00
H FREE ALIGNMENT CHECK								
FAC FAC				352	C	0.00	0.00	
PARTS:				0.00	LABOR:	0.00	OTHER: 0.00	TOTAL LINE H: 0.00
245285 PLEASE SEE ESTIMATE.								

"At Your Service"
 Monday to Friday
 7:00 am - 6:00 pm
 Saturday by appointment

**SERVICE
258-2255**

*Thank you
for
allowing us to
service
your vehicle*

DESCRIPTION	
LABOUR AMOUNT	
PARTS AMOUNT	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
INSURANCE/PAYABLE	
G.S.T.	
	PAY THIS AMOUNT

GST # 828512772 RT0001

We and our service providers and affiliates will use the information provided by you to (i) perform services as may be directly requested by you; (ii) provide more information regarding the products and services of us, our affiliates and business partners. (iii) Generate statistical and aggregated data that does not identify you personally, and (iv) disclose your information to our service providers and affiliates for the purpose of providing services to you and to provide you more information regarding their products and services. By providing your information to us, you consent to these uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.



**HYATT
INFINITI**

CUSTOMER #: 16395
 UNIT# 10012117

283723



**HYATT
INFINITI**

DEERFOOT - CORNER OF HERITAGE
 46 HERITAGE MEADOWS RD. SE
 CALGARY, ALBERTA T2H 3C1
 TELEPHONE: (403) 258-2255 FAX: (403) 258-2458
 www.hyattinfiniti.com

INVOICE

PAGE 3

SERVICE ADVISOR: 615 ROBERT OBRONT


COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG	
BLACK	08	INFINITI FX35	JNRAS08W08X208048	JNE267	245285/245288	T1190	
IN SERVICE DATE	DEL. DATE	WARR. EXP.	PROMISED	PO NO	RATE	PAYMENT	INV. DATE
14FEB08 IS							
14FEB08 DD			15:00 04MAY26		0.00	CASH	04MAY26
R.O. OPENED	READY	OPTIONS: STK:I10012117					
04MAY26	04MAY26						

LINE	OPCODE	TECH	TYPE	HOURS	RETAIL	NET	TOTAL

ESTIMATE: 1,109.80				04MAY26 07:59	SA: 615		
CONTACT:							

#1190

 * HYATT INFINITI RECOMMENDS *
 * RE-TORQUING YOUR WHEEL NUTS *
 * AFTER 100KMS OF DRIVING *
 * - NO APPOINTMENT REQUIRED - *



I N F I N I T I

GST TAX (#: R136888294) 55.89

"At Your Service"
 Monday to Friday
 7:00 am - 6:00 pm
 Saturday by appointment

SERVICE
 258-2255

*Thank you
 for
 allowing us to
 service
 your vehicle*

DESCRIPTION	
LABOUR AMOUNT	640.83
PARTS AMOUNT	368.07
	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	109.00
TOTAL CHARGES	1117.90
INSURANCE/PAYABLE	0.00
G.S.T.	55.89
PAY THIS AMOUNT	1173.79

GST # 828512772 RT0001

We and our service providers and affiliates will use the information provided by you to (i) perform services as may be directly requested by you; (ii) provide more information regarding the products and services of us, our affiliates and business partners. (iii) Generate statistical and aggregated data that does not identify you personally, and (iv) disclose your information to our service providers and affiliates for the purpose of providing services to you and to provide you more information regarding their products and services. By providing your information to us, you consent to these uses. You may notify us in writing if in the future you do not consent to any of these uses of the information you provide.




**HYATT
INFINITI**



Hyatt Infiniti

Automobile Status Report

Prepared For



2008 Infiniti FX35
Date May 04, 2026
VIN JNRAS08W08X208048
Mileage 245285
RO# 283723

Service Advisor

Robert Obront
robmont@hyattinfiniti.com

Multi-Point Inspection Form

VIN JNRAS08W08X208048

Advisor Robert Obront
 Technician TONY Insrichiengmai
 Created On 5/4/2026

Checked and OK at this time May Require Future Attention Requires immediate attention

Interior / Exterior	
<input checked="" type="checkbox"/>	Bulbs and Lights
<input checked="" type="checkbox"/>	Windshield Washer Spray / Wiper Operation / Wiper Blades / Including Rear (if applicable)
<input checked="" type="checkbox"/>	Windshield / Window Condition
<input checked="" type="checkbox"/>	Upholstery / Carpet / Floor Mats / Mirrors / Trim
<input checked="" type="checkbox"/>	Emergency Brake Adjustment
<input checked="" type="checkbox"/>	Horn Operation
<input checked="" type="checkbox"/>	Fuel Tank Cap Gasket
<input checked="" type="checkbox"/>	Clutch Operation (if equipped)
<input checked="" type="checkbox"/>	Cabin/HEPA Filter (if equipped)
Battery Performance	
<input checked="" type="checkbox"/>	Battery Terminals / Cables / Mountings
<input checked="" type="checkbox"/>	Check Condition of Battery (Storage Capacity Test if Applicable)
Under Hood	
<input checked="" type="checkbox"/>	Fluids: Oil / Coolant / Power Steering / Brake Fluid / Washer
<input checked="" type="checkbox"/>	Engine Air Filter
<input checked="" type="checkbox"/>	Belts / Tensioners (condition and adjustment)
<input checked="" type="checkbox"/>	Cooling System Hoses / Heater Hoses / Air Conditioning Hoses and Connections
<input checked="" type="checkbox"/>	Radiator Core / Air Conditioning Condenser (if equipped)

Under Vehicle	
<input checked="" type="checkbox"/>	Shock Absorbers / Suspension
<input checked="" type="checkbox"/>	Steering Gear Box / Linkage and Boots / Ball Joints / Dust Covers
<input checked="" type="checkbox"/>	Muffler / Exhaust Pipes / Mountings
<input checked="" type="checkbox"/>	Engine Oil and/or Fluid Leaks
<input checked="" type="checkbox"/>	Drive Shaft Boots / Constant Velocity Boots / U-joints / Transmission Linkage (if equipped)
<input checked="" type="checkbox"/>	Transmission / Differential / Transfer Case (Check Fluid Level, Fluid Condition and Fluid Leaks)
<input checked="" type="checkbox"/>	Fuel Lines and Connections / Fuel Tank Band / Fuel Tank Vapor Vent System Hoses
<input checked="" type="checkbox"/>	Inspect Nuts and Bolts on Body Chassis
Tread Depth (measured in millimeters")	
<input checked="" type="checkbox"/>	LF <u>5.5</u>
<input checked="" type="checkbox"/>	RF <u>5.5</u>
<input checked="" type="checkbox"/>	LR <u>5.5</u>
<input checked="" type="checkbox"/>	RR <u>5.5</u>
<input checked="" type="checkbox"/>	Spare Tire (if applicable)
<input checked="" type="checkbox"/>	LF/RF Tire Pressure <u>35</u>
<input checked="" type="checkbox"/>	LR/RR Tire Pressure <u>35</u>
Abnormal Wear Pattern of Tires	
<input checked="" type="checkbox"/>	LF
<input checked="" type="checkbox"/>	RF
<input checked="" type="checkbox"/>	LR
<input checked="" type="checkbox"/>	RR
Check Brake Linings (measured in millimeters)	
<input checked="" type="checkbox"/>	LF <u>8</u>
<input checked="" type="checkbox"/>	RF <u>8</u>
<input checked="" type="checkbox"/>	LR <u>5</u>
<input checked="" type="checkbox"/>	RR <u>5</u>


Tie Rod End Replacement: DRIVERS OUTER TIE ROD END. EXCESSIVE PLAY. ALIGNMENT REQUIRED AFTER REPLACEMENT

Item Description

The tie rod end is part of the steering mechanism in a vehicle. The tie rod transmits force from the steering center link or the rack gear to the steering knuckle. This will cause the wheel to turn. The outer tie rod end connects with an adjusting sleeve, which allows the length of the tie rod to be adjustable. This adjustment is used to set a vehicle's alignment angle.

Reason

It is advisable that your vehicle's steering and suspension systems are checked regularly, at least once a year along with a complete wheel alignment. A worn tie rod can cause wandering, erratic steering and also major tire wear.



Tie Rod End


***Alignment: FOUR WHEEL ALIGNMENT INCLUDING ALL ADJUSTMENTS. (vehicles will pull naturally to the right - crown of the road). REQUIRED AFTER TIE ROD REPLACEMENT**

Item Description

Alignment is one of the key maintenance factors in getting the most tread life and performance from your tires. In addition, wheel alignment provides safe, predictable vehicle control as well as a smooth and comfortable ride that's free of pulling or vibration. Today's modern suspensions require a precise four-wheel alignment that can only be achieved through a modern alignment system. This applies to both front and rear wheel drive vehicles. Aligning a car or truck involves the adjustment of the vehicle's suspension, not the tires and wheels. The direction and the angles that the tires point in after the alignment is complete, however, are critically important. There are four factors involved in setting the alignment to specification: caster, camber, toe and ride height.

Reason

If not done, you will see uneven or rapid tire wear, pulling or drifting away from a straight line, and wandering on a straight level road. It can also cause



Alignment

Reason

If not replaced, the engine will leak oil from the valve cover which can result in a burning smell coming from the vehicle's engine.


Spark Plug Replacement 6 Cylinder: SPARK PLUGS

Item Description

The standard spark plug is a spark plug with a center electrode that is made of a material that is not a precious metal. Usually the standard spark plugs are made with copper or nickel center electrodes.

Reason

If your standard spark plug is broken or faulty then your vehicle will have a misfire. The misfire will result in less fuel economy and a loss of power.




**Transmission Fluid Flush: PERFORM AUTOMATIC TRANSMISSION FLUID SERVICE \$399.95+ TAXES

Item Description

A transmission flush is a process that makes it possible to clear the old transmission fluid from the vehicle's transmission. This process also helps to remove residue of older transmission fluid from the converters, coolers, and cooler lines that often are part of the design for the transmission.

Reason

Not conducting a proper transmission flush when needed can cause costly repairs to the transmission unit itself. Neglected transmission fluid cannot properly cool and lubricate a transmission. A lack of lubrication to the transmission's internal components will ultimately lead to a faulty transmission.



AWD DRIVE SERVICE (MOST MODELS): PERFORM ALL WHEEL DRIVE FLUID SERVICE (TRANSFER CASE, FRONT DIFFERENTIAL, REAR DIFFERENTIAL) \$499.95 plus applicable taxes/fees.

Item Description