



GREATWEST KENWORTH LTD

5909 6TH STREET S.E.
CALGARY, AB T2H 1L8
(403) 253-7555

REPRINT CUSTOMER
INVOICE
Work Order
SC1005811

Date: 08-16-19
Page 1 of 2

Table with 6 columns: Year, Make / Model, Serial Number, License, Mileage, Unit/Stock. Includes delivery and engine details.

Table with 7 columns: Engine Hours, Reefer Hours, Standby Hours, P.O. Number, Open Date / Time, Complete, Service Writer.

Memo section header table.

1 KENWORTH PRIVILEGES PROGRAM - ** REGISTER AND SAVE EVEN MORE THROUGH THE KENWORTH LOYALTY REWARDS PROGRAM! **

TOTAL COUPON -33.00

Table with 5 columns: Qty, Part Number, Description, Unit, Extended. Lists various coupons.

2 SQUEAL AT HIGH RPM COMING FROM ENGINE SQUEAL AT HIGH RPM COMING FROM ENGINE CAUSE:

WORN OUT BELTS FOR FAN AND A/C WORN OUT IDLER BEARING ON A/C BELT CORRECTION:

BROUGHT UNIT IN AND THE UNIT WAS NOT SQUEELING. REMOVED BELTS AND CHECKED ALL IDLERS AND TENSIONERS. FOUND THAT THE FAN BELT WAS IN ROUGH SHAPE AND MISSING A RIB.

TOTAL LABOR 159.00
TOTAL PARTS 204.97

Table with 5 columns: Qty, Part Number, Description, Unit, Extended. Lists parts for belt and pulley.

3 A/C NOT WORKING - CHECK AND REPORT A/C N/W

Work Order
SC1005811

Date: 08-16-19

Page 2 of 2

CAUSE:

A/C COMPRESSOR LEAKING

CORRECTION:

CHECK OUT A/C NOT WORKING FIND NO FREON IN SYSTEM HOOK UP NITROGEN PRESSURE TESTER AND SPRAY TO FIND LEAKS FOUND LEAK AT A/C COMPRESSOR REPLACE A/C COMPRESSOR AND RECEIVER DRYER RECHARGE A/C SYSTEM 3 LB 10 OZ TESTED A/C WORKING CORRECTLY 4.5 C DEGREES TO 9 6 C DEGREES

TOTAL LABOR	580.00
ADJUSTMENT	-145.00
TOTAL PARTS	420.35

Qty	Part Number	Description	Unit	Extended
1	LE0122	COMPRESSOR	324.35	324.35
1	GD11350	DRYER-RECEIVER O RING 3"X	42.09	42.09
1	VH11600	KIT- O-RING- HVAC SERVICE	4.47	4.47
4	10953485	R134 FREON	12.36	49.44

4 REPLACE FLEX PIPE UNDER CAB BROKEN FLEX PIPE UNDER CAB

CAUSE:

SMELL EXHAUST COMING IN CAB AND CHECK EXHAUST SYSTEM FIND FLEX PIPE BROKEN UNDER CAB

CORRECTION:

REMOVED AND REPLACED FLEX PIPE

TOTAL LABOR	159.00
TOTAL PARTS	268.50

Qty	Part Number	Description	Unit	Extended
1	M66-6542-0335	PIPE-EXHAUST STR 5"X335 F	251.44	251.44
2	2866337CUM	GASKET-CIRCULAR 5"	8.53	17.06

SHOP SUPPLIES 63.61

G.S.T. - REG. NO. R139766661 5 % OF 1,677.43 = 83.87

CUST MECH LAB-CAL	753.00
PARTS CUSTOMER R/O-CAL	893.82
SHOP SUPPLIES-SHOP A	63.61
INVENTORY ADJUSTMENTS-	-33.00
G.S.T. R139766661	83.87
PLEASE PAY THIS TOTAL	1,761.30

I ACKNOWLEDGE THAT I WILL BE RESPONSIBLE FOR ALL COST INCURRED TO DIAGNOSE, ROAD TEST, DISMANTLE AND REASSEMBLE MY UNIT IF NO FAULT CAN BE FOUND.

THE MANUFACTURER WARRANTY CONSTITUTES ALL OF THE WARRANTIES WITH RESPECT TO THE SALE OF THIS ITEM/ITEMS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESSED OR IMPLIED, INCLUDING AND IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THIS ITEM/ITEMS.

GREATWEST KENWORTH LTD. MAKES THE LIMITED WARRANTY COVERING ANY DEFECT IN WORKMANSHIP OR MATERIAL FURNISHED IN CONNECTION WITH THIS REPAIR ORDER FOR A PERIOD OF THIRTY (30) DAYS FROM THE DATE OF DELIVERY OF SAID MOTOR VEHICLE TO THE CUSTOMER/OWNER, OR 16,000 KILOMETERS WHICHEVER OCCURS FIRST.

IT IS UNDERSTOOD THAT A LIEN MAY BE PLACED THEREON FOR THE AMOUNT DUE IN CASE THE VEHICLE REPAIRS ARE NOT PAID IN FULL.

Customer: X _____ Date: _____

CALGARY -- CLAIRMONT -- LETHBRIDGE -- MEDICINE HAT -- RED DEER