

HEAVY WRENCHING DIESEL LTD

unit #150 - 3303, 57 ave SE
 Calgary, Alberta. T2C 0B2
 (403) 724-1917 Fax: (403) 723-1913
 Writer: JOSEPH SAOUD



INVOICE #8477

info@heavywrenching.com

GST756980694RT0001

CUSTOMER: [REDACTED]	YEAR: 2003	TRANS/DRIVE: NO DATA/RWD
NAME: [REDACTED]	MAKE/MODEL: FORD ECONOLINE E-450	LICENSE/ENGINE /ALBERTA
	VIN: 1FDXE45F13HA24068	KMS IN/ENG. 497179km/
	ENGINE: 7.3L V8 OHV 16V	

In: 6/16/2023 Out: 6/30/2023 Email: PMPATEL456@GMAIL.COM

VEHICLE ISSUE #1: ENGINE SERVICE - AIR FILTER - FUEL FILTER OIL FILTER				
PART	AIR FILTER	2 @ \$34.13	\$68.26	NEW
PART	FUEL FILTER	1 @ \$131.60	\$131.60	NEW
PART	15W-40	15 @ \$5.20	\$78.00	NEW
PART	OIL FILTER	1 @ \$66.70	\$66.70	NEW
LABOR:	PERFORM SERVICE		\$75.00	LABOR
MENGSTEA				

Total for "ENGINE SERVICE - AIR FILTER - FUEL-FILTER OIL FILTER": \$419.56

VEHICLE ISSUE #2: INSPECTION				
TECH REPORT: REAR DIFF SEAL LEAKING RIGHT SIDE AND LEFT SIDE VALVE COVER GASKETS LEAKING UPPER MARKER LIGHTS NOT WORKING BODY DAMAGE BOTH SIDES OF REAR (CRACKING)				
LABOR:	PERFORM INSPECTION		\$250.00	LABOR
MENGSTEA				

Total for "INSPECTION": \$250.00

VEHICLE ISSUE #3: CHECK AC ON FRONT AND REAR - THEY ARE SEPERATE AND BOTH NOT WORKING				
TECH REPORT: AFTERMARKET AC SYSTEM HAS GEAR CLAMPS AND CRACKED LINES - WILL REQUIRE ALL NEW LINES TO CONTINUE DIAG - TRUCK AC COMPRESSOR IS NOT CYCLING AND CAUSING PRESSURES ON LOW AND HIGH TO BE IRRATIC - REQUIRES NEW COMPRESSOR TO CONTINUE DIAG - REPLACED COMPRESSOR BUT LOW SIDE IS LOW ON PRESSURE - CANNOT REMOVE ANY LINES TO TEST FOR ORIFACE TUBE OR LEAKS AS ALL LINES ARE SEIZED.				
PART	FOUR SEASONS COMPRESSOR W/ CLUTCH	1 @ \$589.60	\$589.60	NEW
LABOR:	DIAGNOSE		\$125.00	LABOR
MENGSTEA				
LABOR: SAOUD, M	R/R AC COMPRESSOR		\$187.50	LABOR

Total for "CHECK AC ON FRONT AND REAR - THEY ARE SEPERATE AND BOTH NOT WORKING": \$902.10

VEHICLE ISSUE #4: CHECK 2ND BATTERY PASSENGER SIDE UNDER THE CAB				
PART	NAPA LEGEND BATTERY	1 @ \$252.97	\$252.97	NEW
LABOR:	REPLACE BATTERY		\$125.00	LABOR
MENGSTEA				

Total for "CHECK 2ND BATTERY PASSENGER SIDE UNDER THE CAB": \$377.97

VEHICLE ISSUE #5: REAR DIFF PINION SEAL LEAKING				

Recommended Repairs:	Labor/Jobs	\$1,200.00
	Parts	\$1,226.67
	Sublet	\$0.00
	Total Fees	\$0.00
	Subtotal	\$2,426.67
Warranty: From the date of delivery for a period of 3 months OR 3000km whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. Any signs of negligence will void warranty. A storage fee of \$20 per day will be charged 5 days after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties. RE TORQUE WHEELS AFTER 100KM	Tax @ 5%	\$121.33
	Total	\$2,548.00
	Payments	\$0.00
	Balance	\$2,548.00

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 6/30/2023

HEAVY WRENCHING DIESEL LTD

unit #150 - 3303, 57 ave SE
 Calgary, Alberta. T2C 0B2
 (403) 724-1917 Fax: (403) 723-1913
 Writer: JOSEPH SAOUD



INVOICE #8477

info@heavywrenching.com

GST756980694RT0001



YEAR: 2003
 MAKE/MODEL: FORD ECONOLINE E-450
 VIN: 1FDXE45F13HA24068
 ENGINE: 7.3L V8 OHV 16V

TRANS/DRIVE: NO DATA/RWD
 LICENSE/ENGINE /ALBERTA
 MILES IN/OUT: 497179km

TECH REPORT: REMOVE AND CLEANED REAR PLATE ON HOUSING - RESILICONED AND FILLED DIFF - GOOD			
PART	75W90 FULL SYNTHETIC GEAR OIL	2 @ \$19.77	\$39.54 NEW
LABOR: SAOUD, M	R/R REAR HOUSING PLATE		\$312.50 LABOR
Total for "REAR DIFF PINION SEAL LEAKING": \$352.04			
VEHICLE ISSUE #6: RIGHT AND LEFT SIDE VALVE COVER GAKSETS LEAKING			
TECH REPORT: TIGHTEND COVERS AND CLEANED - NO LEAK FOUND AFTER			
LABOR: SAOUD, M	R/R VALVE COVER GAKSETS		\$125.00 LABOR
Total for "RIGHT AND LEFT SIDE VALVE COVER GAKSETS LEAKING": \$125.00			

Recommended Repairs:	Labor/Jobs	\$1,200.00
	Parts	\$1,226.67
Warranty: From the date of delivery for a period of 3 months OR 3000km whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. Any signs of negligence will void warranty. A storage fee of \$20 per day will be charged 5 days after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties. RE TORQUE WHEELS AFTER 100KM	Sublet	\$0.00
	Total Fees	\$0.00
	Subtotal	\$2,426.67
	Tax @ 5%	\$121.33
	Total	\$2,548.00
	Payments	\$0.00
	Balance	\$2,548.00

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____

Date 6/30/2023