



Banff Service
 (403) 760-4434
 banffservice@gmail.com
 435 Banff Ave, Banff, AB, Canada, T1L 1A8

Invoice # 7161
 Against Estimate#: 12776
 Created: Jan 14, 2025
 Invoiced: Jan 21; 2025



2011 Acura MDX
 VIN: 2HNYD2H6XBH002214
 Mileage in: 268305 km
 Mileage Out: 268305 km
 License Plate:

Customer Notes

Replace the timing belt. Engine making loud clanking noise. Suspect the timing belt tensioner has failed and requires replacement. Do the complete timing belt job and replace the damaged/broken coolant reservoir. If the vehicle starts and runs with no issues we have corrected issue. There is the chance that since this is an interference engine that the pistons and the valves might have contacted each other and could be source of the clank. We have to start with the timing belt replacement.

RADIATOR RESERVE TANK - Remove & Replace

Authorized

Service Notes: Reservoir Was Not Secured Properly And Contacted The Serpentine Belt And Pulley Wheel And Chewed Hole Through Ho using. Requires New Coolant Reservoir And To Be Secured Properly

Item	Name	Description	Price x Qty / Hrs	Amount	Disc./Fees	Subtotal
1	RADIATOR RESERVE TANK - Remove & Replace		\$140.00 x 0.6	\$84.00		\$84.00
2	Engine Coolant Reservoir	19101RYEA00 - Engine Coolant Reservoir	\$49.99 x 1	\$49.99		\$49.99
3	F	FREIGHT	\$30.00 x 1		\$30.00	\$30.00
				Amount:	Disc: \$0.00	Subtotal:
				\$133.99	Fees: \$30.00	\$163.99

Approved by Nadia Bibekir (Online) on Jan 15, 2025 1:37 pm

Maintenance Oil Change

Authorized

Item	Name	Description	Price x Qty / Hrs	Amount	Disc./Fees	Subtotal
1	Engine Oil Change Labour	Oil and filter change Check and correct fluid levels (if equipped with dipstick) Check belts and pulleys Underbody visual inspection Check brakes where visible (wheels on) Visual check on steering & suspension Check and correct all tire pressures	\$140.00 x 0.5	\$70.00		\$70.00
2	Oil Disposal Fee	Enviro Oil Disposal Fee	\$0.30 x 5		\$1.50	\$1.50
3	NAPA Gold Filters Engine Oil Filter	7356	\$19.63 x 1	\$19.63		\$19.63
4	Engine Oil	5W20 Full Synthetic	\$7.99 x 5	\$39.95		\$39.95
				Amount:	Disc: \$0.00	Subtotal:
				\$129.58	Fees: \$1.50	\$131.08

Approved by Nadia Bibekir (Online) on Jan 15, 2025 1:37 pm

TIMING BELT - Remove & Replace

Authorized

Service Notes: Clanking Noise Internal. Possible Tensioner Issue. Recommend Timing Belt Replacement.

Item	Name	Description	Price x Qty / Hrs	Amount	Disc./Fees	Subtotal
------	------	-------------	-------------------	--------	------------	----------



Banff Service
 (403) 760-4434
 banffservice@gmail.com
 435 Banff Ave, Banff, AB, Canada, T1L 1A8

Invoice # 7161
 Against Estimate#: 12776
 Created: Jan 14, 2025
 Invoiced: Jan 21, 2025

1	TIMING BELT - Remove & Replace		\$140.00 x 3.8	\$532.00		
2	AISIN Engine Timing Belt Component Kit	TKH002	\$943.97 x 1	\$943.97		\$943.97
3	NAPA Engine Coolant / Antifreeze	49602BE	\$28.69 x 2	\$57.38		\$57.38

Approved by Nadia Bibekir (Online) on Jan 15, 2025 1:37 pm

Amount: \$1,533.35 Disc: \$0.00 Subtotal: \$1,533.35

TIMING BELT - Remove & Replace (TIMING BELT IDLER PULLEY - Remove & Replace)

Authorized

Service Notes: Part Of The Timing Belt Repair

Item	Name	Description	Price x Qty / Hrs	Amount	Disc./Fees	Subtotal
1	TIMING BELT - Remove & Replace (TIMING BELT IDLER PULLEY - Remove & Replace)		\$140.00 x 0.1	\$14.00		\$14.00

Approved by Nadia Bibekir (Online) on Jan 15, 2025 1:37 pm

Amount: \$14.00 Disc: \$0.00 Subtotal: \$14.00

TIMING BELT - Remove & Replace (TIMING BELT TENSIONER - Remove & Replace)

Authorized

Service Notes: Included In Timing Belt Repair

Item	Name	Description	Price x Qty / Hrs	Amount	Disc./Fees	Subtotal
1	TIMING BELT - Remove & Replace (TIMING BELT TENSIONER - Remove & Replace)		\$140.00 x 0.1	\$14.00		\$14.00

Approved by Nadia Bibekir (Online) on Jan 15, 2025 1:37 pm

Amount: \$14.00 Disc: \$0.00 Subtotal: \$14.00

TIMING BELT - Remove & Replace (WATER PUMP - Remove & Replace)

Authorized

Service Notes: Timing Belt Repair.

Item	Name	Description	Price x Qty / Hrs	Amount	Disc./Fees	Subtotal
1	TIMING BELT - Remove & Replace (WATER PUMP - Remove & Replace)		\$140.00 x 0.3	\$42.00		\$42.00

Approved by Nadia Bibekir (Online) on Jan 15, 2025 1:37 pm

Amount: \$42.00 Disc: \$0.00 Subtotal: \$42.00

Malfunction Indicator Lamp Diagnosis & Testing

Authorized

Service Notes: Dash Light Is On. Noise Heard Coming From Engine. Started Making Noise And Light Came On Yesterday. Noise Coming From Engine. Possible Timing Belt Tensioner Failure. The Coolant Reservoir Is Not Secured In Place And Got Damaged From Contacting The Serpentine Belt.

Item	Name	Description	Price x Qty / Hrs	Amount	Disc./Fees	Subtotal
------	------	-------------	-------------------	--------	------------	----------



Banff Service
 (403) 760-4434
 banffservice@gmail.com
 435 Banff Ave, Banff, AB, Canada, T1L 1A8

Invoice # 7161
 Against Estimate#: 12776
 Created: Jan 14, 2025
 Invoiced: Jan 21, 2025

Diagnosis - General (non-electrical)	Includes: Visual inspection of system components. Connect scan tool, and perform module Self-test, and check for DTCs. Visual inspection MIL electrical harness, connectors, and test MIL control circuit terminal for a short to ground. Does not include: A vehicle road test. Replacement or removal of components. Time for retest system.	\$140.00 x 1	\$140.00	-\$140.00	\$0.00
--------------------------------------	--	--------------	----------	-----------	--------

Approved by Kelly Strevens on Jan 14, 2025 2:26 pm

Amount: \$140.00 Disc: -\$140.00 Subtotal: \$0.00

Date and Time	Receipt No	Payment Method	Amount	Service Amount	
Jan 16, 2025 1:34 pm	12284	Card - Visa xxxx-xxxx-0360 Auth code 07717P	\$2,035.27	Service Amount	\$2,006.92
				Part	\$1,110.92
				Labor	\$896.00
				Add: Fees	\$71.50
				F	\$30.00
				Oil Disposal Fee	\$1.50
				Shop supplies	\$40.00
				Less Discount	\$140.00
				Line Item Discount	\$140.00
				Subtotal	\$1,938.42
				Sales Taxes (GST - 5%)	\$96.85
				Invoice Total	\$2,035.27
				Paid to date	\$2,035.27
				Remaining Balance	\$0.00

By signing this document, you agree to the Terms and Conditions mentioned below.

Signature: _____

Disclaimer:

THANK YOU for your patronage at Banff Service. Did you know we do windshield chips repairs? 12 month/20,000 km North American Warranty. We are a NAPA Autocare Center and an AMVIC Licensed facility. For any parts from outside suppliers, only manufacturers warranty will apply (if any). If you are outside of 40km's of our service location and travelling within Canada or United States, call 1-866-GET-NAPA for any warranty issues. Wheel re-torque required within 100km after any wheel's off service. \$25 PARKING FEE will be charged per day charged after invoicing date. We appreciate your promptness on picking up your vehicle after service is complete. Parking is extremely limited.