

Auto Experts Repair Services Ltd.

Bay 15, 727 - 33 Street NE
Calgary, Alberta. T2A 6M6
Phone: (403)-248-6645 | Fax: (403)-273-6316
autoexpertscalgary.ca | autoexpertsinfo@shaw.ca

Invoice # **058087**
Original Est # 82846

Invoice

Paid Balance Due: **\$0.00**

2009 Jeep - Wrangler - Unlimited Sahara

3.8L, V6 (231CI) VIN(1)

VIN: 1J8GA5915 9L707992

Odometer: In 0 Out 167,567

License Plate: [REDACTED]

Color: Green

Work Complete: 03-05-2026

Service Advisor: TORI HOUSTON

Customer ID: [REDACTED]

Printed Date: 03-05-2026

Type	Description	Part #	Qty	Sale	Total
1 - Transmission issues: Only one gear					\$157.50
Labor	** Road tested and verified transmission issue; the hydraulic pressure is below minimum required levels & overdrive clutch to be gone, causing hard shifting, slipping gears, etc. Also verified bad "death wobble": violent & rapid shaking of front end. ** Inspected and found the track bar, right front outer tie rod, and left front lower ball joint to all have excessive play. Cx decided not to move forward with repairs.				\$150.00

Parts: \$0.00 Labor: \$150.00 Tax: \$7.50 Total: \$157.50

Order **\$9.45**

Misc Shop Supplies \$9.00

Total: \$9.45 Tax: \$0.45

Recommendations

- Airbag MIL on, no horn. Replace clock spring, \$900
- Front axle seal leaking, \$800
- Rear pinion seal leaking, \$400
- Rear wiper nozzle broken, \$400
- Front track bar - EST \$375
- Right front outer tie rod - EST \$320
- Left lower ball joint - EST \$500
- 4WA - EST \$145
- Transmission Asy - EST \$6200

GST # 129023388

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. Warranty on parts and labor is 12 months or 20,000 kilometers whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

ALL WHEEL NUTS MUST BE RETORQUED AFTER 50 KILOMETERS OF DRIVING.

Labor	\$150.00
Parts	\$0.00
Shop Supplies	\$9.00
Subtotal	\$159.00
Taxes	\$7.95
Order Total:	\$166.95

Payment

DIRECT DEBIT Paid \$166.95 on 3-5-2026

Signature _____ Date _____ Time _____
Technician(s) :HJELSVOLD, PARKER

Auto Experts Repair Services Ltd.

Bay 15, 727 - 33 Street NE
 Calgary, Alberta. T2A 6M6
 Phone: (403)-248-6645 | Fax: (403)-273-6316
 autoexpertscalgary.ca | autoexpertsinfo@shaw.ca

Invoice # 05
 Original Est # 81

Invoice

Paid Balance Due: \$0.00

2009 Jeep - Wrangler - Unlimited Sahara

3.8L, V6 (231Ci) VIN(1)

VIN: 1J8GA5915 9L707992

Odometer: In 0 Out 166,713

License Plate: [REDACTED]

Color: Green

Work Complete: 10-22-2025

Service Advisor: ALEX TRABOUL...

Customer ID: [REDACTED]

Printed Date: 10-22-2025

Type	Description	Part #	Qty	Sale	Total
1. General vehicle inspection. Check for oil leak					
Labor	* Completed vehicle inspection. Please view report. Bad oil leak from transmission front seal, smaller leaks from front axle seal and rear pinion seal.				\$94.45
					\$89.95

Parts: \$0.00 Labor: \$89.95 Tax: \$4.50 Total: \$94.45

2. Scan vehicle on-board computer, transmission codes, and clunks goint into gear **\$152.25**

Labor	* Road test and verified transmission not shifting properly. Scan vehicle and retrieved engine/transmission codes 'P0731 and P0732 gear ration error 1st and 2nd gear. Inspected further and located connector for pressure switch off. Re-connected harness, cleared codes and road test. Transmission shifting properly now and fault code did not return. Please monitor.				\$145.00
-------	--	--	--	--	----------

Parts: \$0.00 Labor: \$145.00 Tax: \$7.25 Total: \$152.25

Order **\$14.81**

Misc Shop Supplies \$14.10

Total: \$14.81 Tax: \$0.71

Recommendations

- Airbag MIL on, no horn. Replace clock spring, \$900
- Front axle seal leaking, \$800
- Rear pinion seal leaking, \$400
- Rear wiper nozzle broken, \$400

1150.00
 320.00 225.

 345.00

 1150.
 (1865.00)

GST # 129023388

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. Warranty on parts and labor is 12 months or 20,000 kilometers whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

ALL WHEEL NUTS MUST BE RETORQUED AFTER 50 KILOMETERS OF DRIVING.

Labor	\$234.95
Parts	\$0.00
Shop Supplies	\$14.10
Subtotal	\$249.05
Taxes	\$12.45
Order Total:	\$261.50

Payment

DIRECT DEBIT Paid \$261.50 on 10-22-2025

Signature _____ Date _____ Time _____
 Technician(s) : HUYNH, CHI 002

Auto Experts Vehicle General Inspection.

Auto Experts Repair Services Ltd.

Bay 15, 727 - 33 Street NE

Calgary, Alberta T2A 6M6

Phone: 403-248-6645

Name: [REDACTED]

Y/M/M: 2009 Jeep Wrangler

VIN: 1J8GA59159L707992

License: [REDACTED]

Mileage: _____

Date Completed: In Progress

Test Drive	G	Y	R
Malfunction Indicator Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Front Wiper Blades / Washers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Wiper Blade / Washers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windshield Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Conditioning	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
HVAC Blower Motor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Exterior lights	G	Y	R
Headlights / Lens	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Brake lights / Lens	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Signal lights / Lens	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Park / Tail Lights / Lens	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Daytime Running Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
License Plate Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fog / Driving Lights / Lens	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Under carriage/leaks	G	Y	R
Exhaust System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Drive Axles / Shafts / CV Boots	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Drive Axles / Shafts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Engine Oil Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission / Transaxle	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Under carriage/leaks	G	Y	R
Brake Fluid Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Coolant Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Drive Train Fluid Condition / Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Underhood/fluids	G	Y	R
Coolant Condition / Level	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Engine Oil Condition / Level	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Brake Fluid condition / level	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Washer fluid/top-up	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Steering Fluid / condition level: service			
Transmission Fluid condition / level: good			
Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cabin filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hoses	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Radiator	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Battery Clamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Battery Load Test	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Drive Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Suspension/Steering	G	Y	R
Springs / Torsion Bars	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Auto Experts Vehicle General Inspection.

Auto Experts Repair Services Ltd.

Bay 15, 727 - 33 Street NE

Calgary, Alberta T2A 6M6

Phone: 403-248-6645

Horn

horn not working, AIRBAG codes stored

Park / Tail Lights / Lens

both front marker lamps out

Drive Axles / Shafts / CV Boots

Rear pinion seal leaking, small.

Drive Axles / Shafts

front axle seal small leak.

Transmission / Transaxle Leaks

transmission front seal leaking bad.

Ball Joints

right upper and lower ball joint little endplay