

The Alberta Superintendent of Insurance has approved this form pursuant to section 803 of the *Insurance Act*.

## **AUTOMOBILE INSURANCE MOTOR VEHICLE INSPECTION REPORT**

This Report is required only if the vehicle is 12 years or older and must be completed by a licensed mechanic.

Applicant/Insured Name:	Vehicle Make: HOND A
Policy Number:	Vehicle Model: PRPLUDE 2 dr
VIN#: JHMBB614 XWC802133	Vehicle Year: 1998

This Section to be completed by a Licensed Mechanic

	Roadworthy	Reject		Roadworthy	Reject
Steering		Electrical System			
Steering Box/Rack			Head Lamp/Tail Lamps		
Struts/Shocks	سر:		Stop Lamps		1
Front Suspension	نسرة ا		Signal Lamps		
Tie Rod Ends	i í		Windshield Wipers	V	
Tires		•	General Conditions		
Front	2		Body Condition		
Rear			Muffler/Exhaust		
Brakes			Motor	·	
Front Lining or Drums	نسمين .		Windshield	<u>ب</u>	
Rear Lining or Drums	5000		Seat Belts	<b>S</b> eculiarian	
Park			Has the vehicle been altered for speed or performance?	□YES	□ NO
Brake Hoses	<b>/</b>				
Brake Lines			Is the vehicle roadworth	y ØYES	□ NO

Mechanic's Statement: I certify that I have inspected and tested the motor vehicle described above and found it to be in the condition stated above.

Date:	30708-24		
Signature of Qualified Mechanic: Mechanic's Certificate No.:	9029 T		
Automotive Repair Shop Name:			
Address: Telephone Number:	Activis Oslobs Lil.  16, 22 is to construct.  Oslobs, About Vil 1648		
	<b>100</b> (100) 261-0025		