



Automobile Insurance Motor Vehicle Inspection Report

This report is for insurance underwriting purposes only.

The Alberta Superintendent of Insurance has approved this form pursuant to section 803 of the Insurance Act.

This report is required only if the vehicle is 12 years or older and must be completed by a Certified Automotive Technician.

Vehicle Owner's Name [REDACTED]		Insurance Company	
Insurance Broker		Policy Number [REDACTED]	
Vehicle Year 2011	Make Nissan	Model Murano SL	VIN JN8AZ1MW3BW1553

This section is to be completed by a Certified Automotive Technician.

Steering	Roadworthy	Reject	Comments
Steering Box/Rack	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Struts/Shocks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Front Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Tie Rod Ends	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Electrical System	Roadworthy	Reject	Comments
Head Lamp/Tail Lamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Stop Lamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Signal Lamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Windshield Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Tires	Roadworthy	Reject	Comments
Front	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Rear	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Brakes	Roadworthy	Reject	Comments
Front Lining or Drums	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Rear Lining or Drums	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Park	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Brake Hoses	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Brake Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
General Conditions	Roadworthy	Reject	Comments
Body Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Muffler/Exhaust	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Motor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Windshield	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Seat Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Is this vehicle roadworthy? Yes No Has the vehicle been altered for speed or performance? Yes No

Other Comments

Certified Automotive Technician Statement:

I certify that I have inspected and tested the motor vehicle described above and found it to be in the condition stated above.

Name of Automobile Repair Shop OAKRIDGE AUTOMOTIVE		Address	
City 9405 - 24TH ST SW CALGARY, AB T2V0K7	Province/Territory AB	Postal Code	Telephone Number J
Certified Automotive Technician's Name Anwar Ahmad		Certified Automotive Technician's Certificate Number J-13-111647	
Date (yyy-mm-dd) 2026-02-20		Certified Automotive Technician's Signature <i>A. Ahmad</i>	



Oakridge Automotive

9405 24th St. SW
Calgary, AB T2V0K7
Phone: 403-281-1353

2/20/2026 4:44:00PM

Invoice #
83919

oakridgeautoselect@gmail.com

2011 Nissan Murano SL DARK BLUE

Odometer Out: 216612

License: CYH4753

VIN: JN8AZ1MW3BW155533

Eng: 3.5L, V6 (213CI) VIN(A)

Manufactured: 02/20/2026

Description Of Services

INSURANCE INSPECTION

Perform inspection for certification of roadworthiness as per insurance company guidelines and manufacturer's specifications. Includes road test. Provide customer with inspection findings.

Vehicle Memo

10/10

Labor: \$99.95 Parts: \$0.00 Sublet:\$0.00 Subtotal: \$99.95

MUFFLER AND TAIL PIPE ASSEMBLY - Remove & Replace

Part Number	Description	Quantity	Sale	Extended
54808	MUFFLER-QUIETFLOWSS-IMP TK	1.00	\$687.12	\$687.12
36400	HARDWARE - TIP	2.00	\$118.98	\$237.96
31307	GASKET	1.00	\$6.24	\$6.24

Labor: \$85.00 Parts: \$931.32 Sublet:\$0.00 Subtotal: \$1,016.32

FRONT STABILIZER BAR LINK ASSEMBLY - Remove & Replace - Both Sides - [DOES NOT include wheel alignment]

Part Number	Description	Quantity	Sale	Extended
MS30879	STABILIZER BAR LINK KIT	2.00	\$87.42	\$174.84

Labor: \$102.00 Parts: \$174.84 Sublet:\$0.00 Subtotal: \$276.84

Service Advisor: POTTER, TERRY
Technician(s): AHMAD, ANWAR; Please Select, Technician

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

I hereby authorize to pay the above invoice, and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. All services come with Roadside Assistance for 1 year, coverage is \$75.00. Phone number to call is 1-855-276-9297.

PLEASE REVIEW US ON GOOGLE

ALL VEHICLES IN FOR SERVICE OR REPAIR REQUIRE A RE-TORQUE OF THE WHEEL LUG NUTS BETWEEN 75-100KMS.

Labor Total:	\$286.95
Parts Total:	\$1,106.16
Shop Sup.:	\$0.00
HazMat:	\$0.00
Sub Total:	\$1,393.11
Tax Total:	\$69.66
Grand Total:	\$1,462.77
Balance Due:	\$1,462.77



SIGNATURE.....Date.....

