



Crucial Diesel
 9 Charles Industrial Way
 Sylvan Lake, AB. T4S 0B6
 Phone: 403-887-5507

INVOICE

7816

Org. Est. # 008418

INVOICE

Printed Date: 03/23/2026

Work Completed: 03/23/2026

1999 Ford - Pickup F250 Super Duty - 7.3L, V8 (444CI) VIN(F)

Lic # : CHJ-2487

Odometer In : 258824

VIN # : 1FTNX21F3 XED40157

Part Description	Qty	Sale	Ext	Labor Description	Ext
Valve cover gasket harness assembly	1.00	120.00	120.00	Diag crank no start, has smoke out tailpipe	700.00
Glow Plug	8.00	37.50	300.00	Verified crank no start and smoke out the tail pipe. Pushed into shop and find glow plug relay functions correctly but 7 of 8 glow plugs have low reading and 1 excessive reading. Remove valve covers to inspect wiring harnesses and find drivers side valve cover has an open, replaced drivers side valve cover. Test glow plugs individually ant find 1 @ 2.3 Kohms all others below 0.5ohm proper spec is 1ohm. Replaced all 8 glow plugs. Truck now starts and drives properly.	
Shop Supplies			35.00		

Note Airbag and ABS lights on previous to repairs.

Org. Estimate 1,212.75 Revisions 0.00 Current Estimate 1,212.75

Labor:	700.00
Parts:	455.00
SubTotal:	1,155.00
Tax:	57.75
Total:	1,212.75
Bal Due:	\$1,212.75

[Payments -]

Vehicle Received: 3/23/2026

Customer Number : 2557

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 20,000kms whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

GST# 734821689RT0001

Signature _____ Date _____

Visit us on the web: <https://crucialdiesel.com/>

Email Address: crucialdiesel@outlook.com