Inspection Report - Truck/Trailer



Date: OCT 15/24	Elect Hrs:Engine Hrs: 4452
Customer: REGAL AUCTIONS	Total Hrs: Set Point:
Make: CARRIER Model: VECTOR	Location: YARD
Truck / Trailer #: <u>002 309</u> Unit #:	Inspected by: STREAMLINE
Needs	Needs
OK Attention Notes	OK Attention Notes
Visual	Structural
Drive Belt	Doors, Hinges, Latches.
Alernator and	Skins
Alt. Belt	Mounting, Frame.
Water Pump	Operational
Condenser / Radiator	
Air Intake Hoses	Status Lights
Air Filter DUE	Start Up/Abnormal Noises Running/Abnormal Noises
Coolant Hoses /	Defrost System.
Clamps	Idlers and Fan Shaft
Exhaust System.	Clutch, Connections
Wiring	(Electric Standby)
Throttle Solenoid, Linkage and Boot*	Fuel Tank
Coolant Level	Fuel Decal*
Coolant Condition	Fuel Lines/Leaks
Battery Holdown	Fuel Tank Vent*
Battery & Connections.	Fuel Tank Mounts*
Engine Oil Level. SERVICE DUE	Fuel Tank Gauge*
Refrigeration Lines	Inside Trailer or Truck Body
Oil Leaks	
Transfer Pump*	Box Insulation
Electric Fuel Pump	Door Seals
The state of the s	and Flapper Valves.
Additional Notes FUEL SENSOR FAILED	RA Bulkheads, Floor Channels, Chute
TENSUR FILLER	Damper Linkage,
	Bushings & Springs
	cvaporator
	CTDCAMI INC

STREAMLINE TOO