



National Transmission

Operated by Cypress Transmissions (2013) Ltd.

4701 Macleod Trail S
Calgary, AB T2G 0A7
(403) 243-6114

Date	Invoice #
6/29/2022	8405

Invoice To

Please
REVIEW US!
Google
★★★★★

Year	Make	License No.	Mileage	Transmission type	Vehicle Serial No.
2006	Toyota Matrix		283718	5SP 1.8L	2T1KR32E96C591176

Quantity	Item	Description	Price Each	Amount
	CC1	Customer Comment -Slipping uphill or on acceleration	0.00	0.00
	REF Retail	How did you hear about National Transmission - Email	0.00	0.00
	TT1	Technician Comment - Road test confirms clutch slippage, Has minor engine leak. Requires new clutch and flywheel	0.00	0.00
8.8	Labour	Replace clutch and flywheel	130.00	1,144.00
1	Part	clutch kit	329.98	329.98
1	Part	Flywheel	224.00	224.00
1	SH	Shop supplies (minor repair)	84.90	84.90
1	EPA	Environmental charge	14.95	14.95
	MC	Paid by Mastercard	0.00	0.00
		GST on sales	5.00%	89.89

The parts and labour operations charged on this invoice are guaranteed for a period of 12 month UNLIMITED km. at this center only (unless otherwise stated). If your transmission malfunctions (regardless of your location) phone this center. Do not use the vehicle or permit repairs until authorized by this center. Towing, consequential cost, and abuse are not covered under this guarantee. In any event, the amount for which this center shall be liable shall not exceed the amount on this invoice. Note: external electrical problems can cause malfunctions and failures of the transmission which are not covered under the guarantee. The guarantee is non-transferable.

GST/HST No. 824249734

Subtotal \$1,797.83

Total \$1,887.72

Authorization/Acceptance X. _____

**MINT AUTO SERVICE WESTBROOK**

3809-17th Avenue SW
GST: 894540863R
Licence: EL12869
CALGARY, AB T3E-0C3
Tel: (403) 242-6631
info@speedyservicewest.com • www.mintautoservice.ca

Invoice MW012111

Service Advisor: Travis Brown
Technician: BRYAN GALLINGER
Date: 1-24-2024
Estimate: Q003507
R/O: J014100

Customer

Alternative Contact:

Vehicle 2006 Toyota Matrix Base
1.8 GAS
2T1KR32E96C591176

Miles In: 299,999
Miles Out: 299,999
License Plate: **£30,900**

**Customer Issues and
Advisories**

Work Description
EXHAUST INSPEC

Work Performed**PERFORM COMPLETE EXHAUST SYSTEM INSPECTION FOR LEAKS**

Labor	Tech	Hrs	Price	Discount	Total
EXHAUST LABOUR		1.50	149.99	0.00%	224.99
PERFORM COMPLETE EXHAUST SYSTEM INSPECTION FOR LEAKS		1.00	49.95	100.00%	0.00

Parts	Part No	Qty	Price	Discount	Total
RESONATOR-DIRECT FIT ASSY	WLK54698	1.00	245.71	0.00%	245.71
SPRING-BOLT KIT	WLK35129	1.00	23.41	0.00%	23.41
CLAMP	WLK35335	2.00	4.67	0.00%	9.34
PIPE-DIRECT FIT	WLK52453	1.00	100.99	0.00%	100.99
GASKET	WLK31533	1.00	42.12	0.00%	42.12

PERFORM COMPLETE EXHAUST SYSTEM INSPECTION FOR LEAKS SubTotal **\$646.56**

Complimentary Inspection

Labor	Tech	Hrs	Price	Discount	Total
LIGHT 45 SAFETY INSPECTION : DRIVEABILITY, SUSPENSION,BRAKES,ENGINE,EXHAUST,TIRES , GENERAL VEHICLE VISUAL CONDITION		0.50	0.00	0.00%	0.00
Complimentary Inspection		1.00	0.00	0.00%	0.00

Complimentary Inspection SubTotal **\$0.00**

Total

Labor 224.99
Parts 421.57
Hazmat* 0.00
Supplies* 22.50
GST/HST 33.47
PST 0.00

Invoice Total \$702.53

* Shop Supply & Hazmat Fees: This charge represents costs (where applicable) to this repair facility for miscellaneous shop supplies, and/or waste removal

Douglas Square Auto Service

Bay 102 11540 24th St. SE

Calgary, AB T2Z3K1

Phone: 403-720-8010 Fax: 403-720-8031

11/10/2025

Invoice #

99104



2006 Toyota Matrix SILVER

Odometer In: 299999

License:

VIN: 2T1KR32E96C591176

Eng: 1.8L, In-Line4 (109CI)

Description Of Services

INSURANCE INSPECTION

INSURANCE INSPECTION

Perform inspection for certification of roadworthiness as per insurance company guidelines and manufacturer's specifications. Includes road test. Provide customer with inspection findings.

- WIPER BLADES POOR.
- FT BRAKES DUE. DISC ROTORS HEAVY RUST.
- OIL LEAK FROM OIL SENDER ASSY.
- OIL LEAK TIMING CHAIN TENSIONER.
- STEAM CLEAN ENGINE OFF.

NOTE; REAR DRUM BRAKES GOOD 60% APPROX.

- WINTER TIRES 8/32 GOOD. SLIGHT ROAD NOISE.

Labor: \$79.95

Parts: \$0.00

Sublet: \$0.00

Job Total: \$79.95

FRONT BRAKE RELINE

Labour to replace front disc brake pads, remove brake rotors for machining or replacement, and clean and lube caliper slides. Road test to verify part integrity and workmanship. Auto Select provides Limited Lifetime Warranty on premium brake pads.

Part Number	Description	Quantity	Sale	Extended
WS1-231270	COATED BRAKE ROTOR/Disc Brake Rotor (Front)	2.00	\$96.66	\$193.32
WSD923CH	CERAMIC PAD SET/Disc Brake Pad Set (Front)	1.00	\$128.88	\$128.88

Labor: \$190.80

Parts: \$322.20

Sublet: \$0.00

Job Total: \$513.00

OIL PRESSURE SENDER OR SWITCH - Remove & Replace

Part Number	Description	Quantity	Sale	Extended
PS305T	SWITCH - OIL PRESSURE/Engine Oil Pressure Switch	1.00	\$55.88	\$55.88

Labor: \$79.50

Parts: \$55.88

Sublet: \$0.00

Job Total: \$135.38

TIMING CHAIN TENSIONER RESEAL- Remove & Replace SEAL- Eng VIN R,Eng CD 1ZZ-FE

Part Number	Description	Quantity	Sale	Extended
90301-22013	Chain Tensioner O-Ring	1.00	\$3.46	\$3.46

Labor: \$143.10

Parts: \$3.46

Sublet: \$0.00

Job Total: \$146.56

ENGINE CLEAN FOR OIL LEAKS.

Labor: \$0.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$0.00



GST #: 897273827

Page 1





Automobile Insurance Motor Vehicle Inspection Report

This report is for insurance underwriting purposes only.

The Alberta Superintendent of Insurance has approved this form pursuant to section 803 of the *Insurance Act*.

This report is required only if the vehicle is 12 years or older and must be completed by a Certified Automotive Technician.

Vehicle Owner's Name		Insurance Company	
Insurance Broker		Policy Number	
Vehicle Year 2006	Make TOYOTA	Model MATRIX	VIN 2T1KR32E96C591176

This section is to be completed by a Certified Automotive Technician.

Steering	Roadworthy	Reject	Comments
Steering Box/Rack	☒	☐	
Struts/Shocks	☒	☐	
Front Suspension	☒	☐	
Tie Rod Ends	☒	☐	
Electrical System	Roadworthy	Reject	Comments
Head Lamp/Tail Lamps	☒	☐	
Stop Lamps	☒	☐	
Signal Lamps	☒	☐	
Windshield Wipers	☒	☐	
Tires	Roadworthy	Reject	Comments
Front	☒	☐	
Rear	☒	☐	
Brakes	Roadworthy	Reject	Comments
Front Lining or Drums	☒	☐	
Rear Lining or Drums	☒	☐	
Park	☒	☐	
Brake Hoses	☒	☐	
Brake Lines	☒	☐	
General Conditions	Roadworthy	Reject	Comments
Body Condition	☒	☐	
Muffler/Exhaust	☒	☐	
Motor	☒	☐	
Windshield	☒	☐	
Seat Belts	☒	☐	

Is this vehicle roadworthy? ☒ Yes ☐ No Has the vehicle been altered for speed or performance? ☐ Yes ☒ No

Other Comments

Certified Automotive Technician Statement:

☒ I certify that I have inspected and tested the motor vehicle described above and found it to be in the condition stated above.

Name of Automobile Repair Shop DOUGLAS RD AUTO SERVICE		Address	
City #102, 11500-26 ST. SE CALGARY AB T2Z3K1	Province/Territory AB	Postal Code	Telephone Number 403 720 8010
Certified Automotive Technician's Name MICHAEL KEARNEY		Certified Automotive Technician's Certificate Number 2900BP	
Date (yyyy-mm-dd) 2025/11/10		Certified Automotive Technician's Signature	