

6417 Highway #97 N Vernon, BC V1B3R4 Phone: (250) 542-0371 www.vernonnissan.com service@Vernonnissan.com

## SO# 105921

## SERVICE ORDER



Printed 08/29/2024 2:48:54 PM CUSTOMER COPY

User

JADEN Page

Advisor Wayne Promised 05/04/2018 12:00 AM Tag# Shop Opened 04/30/2018 12:00 AM Location Priority Cashiered 05/04/2018 12:00 AM PO #

Odom In Odom Out In Service Date Stock No 95699 95699 05/31/2013 Year Make Model **Model Number** Colour 2013 NISSAN **PATHFINDER** Silver

|                   | Vehicle ID No<br>5N1AR2MMXDC667502<br>Engine   | Selling Dealer  | Extended Warranty<br>ASP NEW |         | Delivery Date<br>01/07/2017 |          |
|-------------------|--|---|------------------------------|---------|-----------------------------|----------|
| Request<br>JD01AA | Description  | 6.  |                              | Job     | CSR                         | Status   |
| Labour            | R&I AUTOMATIC CVT TRANSAX LE ASSY *  |   |                              | 1       | WAYNE                       | Original |
| JD01AA            | Description  |   |                              |         | Type                        | Amount   |
| JD01AA<br>JD023A  | R&I AUTOMATIC CVT TRANSAXLE ASSY *   |   | *                            |         | W                           |          |
| JX31AA            | COMBINATION: RPL AUTOMATIC CVT TRANSAXLE ASSY FLUSH CVT OIL COOLER   |   |                              |         | W                           |          |
| JD20AA            | add on trans code  |   |                              |         | W                           |          |
| JE99AA            | REPROGRAM A/T CONTROL UNIT   |   |                              |         | W                           |          |
| Part              |  | 01  | D                            |         | . W                         |          |
| PART1             | Description PART TOTAL   | Shp   |                              | oe<br>W | Price                       | Amount   |
| Technician        | 17 -   | ı   | Est Parts                    | VV      |                             | 0.00     |
| Cause             | CUSTOMER REPORTS THE TRANSMISSION WILL NOT SHI<br>HEARS GROWLING SOUND OUTSIDE OF THE VEHICLE  | FT UPHILLS,   | Est Labour                   |         |                             | 0.00     |
| Correction        | 95695 confirm noise traced to transmission while driving (Inte no codes. Fluid level is correct. Can smell that fluid is clearly bu metal particles in it. (Internal issue inside transmission and will remove cvt assy and replace. Replace exhaust gaskets, axle n bolts. flush oil cooler and external cooler. program tcm and adjudrive and noise is now gone. | rnt and has some<br>require new.<br>luts, drive shaft |                              |         |                             |          |
| Request           | Description  |   |                              | Job     | CSR                         | Status   |
| RC                | CHECKED VEHICLE FOR ANY O UTSTANDING RECALLS   |   |                              | 2       | WAYNE                       | Original |
| Labour            | Description  |   |                              |         | Type                        | Amount   |

| RC<br>Labour<br>RC<br>Technician | CHECKED VEHICLE FOR ANY O UTSTANDING RECALLS  Description  CHECKED VEHICLE FOR ANY OUTSTANDING RECALLS  99 - | Est Dest.  | 2   | WAYNE<br>Type | Original<br>Amount |  |
|----------------------------------|--|------------|-----|---------------|--------------------|--|
|                                  |  | Est Parts  |     |               | 0.00               |  |
| Cause                            | CHECKED VEHICLE FOR ANY OUTSTANDING RECALLS  | Est Labour |     |               | 0.00               |  |
| Request                          | Description  |            | Job | CSR           | Status             |  |
| RC                               | CHECKED VEHICLE FOR ANY O UTSTANDING RECALLS   |            | 3   | WAYNE         | Original           |  |
| Labour                           | Description  |            |     | Type          | Amount             |  |
| RC                               | CHECKED VEHICLE FOR ANY OUTSTANDING RECALLS  |            |     | ا             | runount            |  |
| Technician                       | 99 -   | Est Parts  |     |               | 0.00               |  |
| Cause                            | CHECKED VEHICLE FOR ANY OUTSTANDING RECALLS  | Est Labour |     |               | 0.00               |  |

G.S.T. #797858818

CHECAUE CHARGE CASH C DEDUCTIBLE : CREDIT CARD INDEBTEDNESS IS HEREBY ACKNOWLEDGED FOR THE "TOTAL CHARGES" & BEING ALL OR THE BAL ANCE OWING TO REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (27% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS. BEING ALL OR THE BAL-

CUSTOMER SIGNATURE DATE



6417 Highway #97 N Vernon, BC V1B3R4 Phone: (250) 542-0371 www.vernonnissan.com service@Vernonnissan.com

SO# 105921

Printed

08/29/2024 2:48:54 PM

## SERVICE ORDER CUSTOMER COPY

Wayne

S1

Advisor

Shop

Priority

ENDOCACIONES EN CONTROL DE CONTRO

Page

JADEN

PY User

Promised

Cashiered

Opened

05/04/2018 12:00 AM Tag# 04/30/2018 12:00 AM Location

05/04/2018 12:00 AM PO #

Odom Out In Service Date Stock No Odom In 95699 95699 05/31/2013 Year Make Model Model Number Colour Silver 2013 NISSAN **PATHFINDER** Vehicle ID No **Delivery Date** Selling Dealer **Extended Warranty** 01/07/2017 ASP NEW 5N1AR2MMXDC667502 Engine

 Labour
 0.00

 Parts
 0.00

 Supplies
 0.00

 Sub-Total
 0.00

 Total Invoice
 0.00

G.S.T. #797858818

CHEQUE = CHARGE = CASH = DEDUCTIBLE = CREDIT CARD =

DATE

INDEBTEDNESS IS HEREBY ACKNOWLEDGED FOR THE "TOTAL CHARGES" & BEING ALL OR THE BAL-ANCE OWING TO REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (27% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE