

2009 Chrysler Vehicle Diagnostic Report

Vehicle Information

2009/Chrysler/DS-Ram 1500/
VIN: 1D3HV18T19S824722

Odometer Reading: 316323.5km
License Plate: --

Customer Information

Name: --

Tel: --

Device information

Scanner: MaxiSys MS906 Pro-TS
Version: V6.40

Serial Number: VA6GP8V01080
Repair Order Number:
VA6GP8V0108020260812141101334

 System Scanned(16)

System	Status/DTC
ECM(Engine Control Module)	✓ 0
DTCM(Drive Train Control Module)	✓ 0
ABS(Anti Lock Brakes)	✓ 0
ORC(Air Bag/Occupant Restraint)	✓ 0
MIC/CCN(Mechanical Instrument Cluster)	✓ 0
CGW(Central Gateway)	✓ 0
SAS(Steering Angle Sensor)	✓ 0
RADIO(Radio)	✓ 0
HVAC(Heat, Ventilation And A/C)	✓ 0
AMP(Amplifier)	✓ 0
PTS(Parktronics)	ADAS ✓ 0
HSM(Heated Seat Module)	✓ 0
WCM/TPMS(Wireless Control)	✗ 4
MSM(Memory Seat/Memory Heated Seat)	✓ 0
DMFR(Door Module Front Right)	✓ 0
DMFL(Door Module Front Left)	✓ 0

 DTC (4)

WCM/TPMS(Wireless Control) (4 DTCs)

DTC	Description	Status
C1503	Tire pressure sensor 3 internal	Active

C1501	Tire pressure sensor 1 internal	Active
C1502	Tire pressure sensor 2 internal	Active
C1504	Tire pressure sensor 4 internal	Active

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.