



Out of Province Vehicle Inspection Certificate
Traffic Safety Act


PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Automotive	Seating Capacity:	
GVW:		Brake Type:	Hydraulic
Owner Name:			
Address:			
City:		Province:	
Postal Code:			
Telephone Number:	(587) 223-2680		
Vehicle Identification Number:	JA4AT3AA5LZ609311		
Make:	Mitsubishi	Model:	Eclipse
Year:	2020	Unit Number:	
Odometer:	97393 KM	Licence Plate Number:	
Province:	BC		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Out of Province Vehicle.

Inspection Facility Name:	Facility Number:
Cedar Automotive and Tire Services Ltd.	19655
Inspection Technician Name:	Technician Number:
Ali Soboh	C5586
Inspection Technician Signature:	
Inspection Date:	2026/08/26

NOTICE TO VEHICLE OWNER

1. This inspection certificate expires after 14 days from the Inspection date. After 14 days, a complete re-inspection of the vehicle is required.
2. The original of this Certificate must be presented to an Alberta Registry Agent within 14 days; however, there is no requirement to register the vehicle when the certificate is presented.

MOTOR VEHICLE RECORD OF INSPECTION

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Vehicle Information																	
VIN	J	A	4	A	T	3	A	A	5	L	Z	6	0	9	3	1	1
Make Mitsubishi				Model Eclipse				Year 2020				Odometer 97393					
Customer Information																	
Last Name MASOOD								First Name JAHANGIR									
Address 102 NOLANCLIFF CRES NW													Postal Code T3R-0S6				

Section 1 - Pre-Inspection

Component	P	F	NA	Component	P	F	NA
1.1a. Request for Inspection (RFI)	✓			1.3c. Vehicle Wanders or Pulls	✓		
1.1b. Vehicle Accurately Described On The RFI	✓			1.3d. Brake System Performance	✓		
1.2a. VIN Plate Condition	✓			1.3e. Driveability	✓		
1.2b. VIN Consistent With RFI	✓			1.3f. Speedometer Operation	✓		
1.3a. CV Joint Road Test Result	✓			1.3g. Odometer (if equipped) Operation	✓		
1.3b. Universal Joint Road Test Result	✓						

NOTES:

Section 2 - Onboard Diagnostic Systems

Component	P	F	NA	Component	P	F	NA
2.1a. PCM Codes Present	✓			2.4b. SRS Lamp Fails To Illuminate	✓		
2.1b. PCM (MIL, SES, etc) Lamp Fails To Illuminate	✓			2.4c. SRS Lamp Remains Illuminated	✓		
2.2a. ABS Codes Present	✓			2.4d. Airbag(s) Present	✓		
2.2b. ABS Lamp Fails To Illuminate	✓			2.4e. Airbag Cover Integrity	✓		
2.2c. ABS Lamp Remains Illuminated	✓			2.5. Electronic Stability Control (ESC)	✓		
2.3a. Brake System Warning Lamp Fails To Illuminate	✓			2.6. Powertrain Warning Lamps	✓		
2.3b. Brake System Warning Lamp Remains Illuminated	✓			2.7. Other Safety Systems	✓		
2.4a. SRS Codes Present	✓						

NOTES:

BACKUP CAMERA

Section 3 - Interior

Component	P	F	NA	Component	P	F	NA
3.1. Doors	✓			3.11. Instrument Panel Lamps	✓		
3.2. Rear View Mirror	✓			3.12. HVAC	✓		
3.3. Sun Visors	✓			3.13. Windshield Wiper and Washer Operation	✓		
3.4. Horn	✓			3.14. Accelerator	✓		
3.5. Seats	✓			3.15. Service Brake Pedal	✓		
3.6. Seatbelts	✓			3.16. Clutch Pedal Assembly	✓		✓
3.7. Signal Lamp Switch and Indicator	✓			3.17. Park Brake	✓		
3.8. Hazard Lamps	✓			3.18. Neutral Safety Switch Operation	✓		
3.9. Headlamp Switch and High Beam Indicator	✓			3.19. Entertainment Display Lockout	✓		
3.10. Auxiliary Lamp Indicator(s)	✓						

NOTES:

FOG LIGHTS

MOTOR VEHICLE RECORD OF INSPECTION

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tread Depth- LF:7 mm,RF:7 mm,LR:7 mm,RR:7 mm	✓			9.4. Tire Serial Numbers & Dates of Manufacture	✓		
9.2. Tire Condition (general)	✓			9.5. Wheels	✓		
9.3. Tire Size	✓			9.6. Wheel Nuts and Studs	✓		

NOTES:

225/55R18 102T
MILE KING WINTER MK687
DOT 133A4RCTC 4222

Section 10 - Brakes

Component	P	F	NA	Component	P	F	NA
10.1. Brakes (general)	✓			10.6. Park Brake Drum Diameter- LR:0.00 mm,RR:0.00 mm			✓
10.2. Park Brake Lining- LR:0.00 mm,RR:0.00 mm			✓	10.6. Brake Rotor Thickness- LF:25.87 mm,RF:25.87 mm	✓		
10.2. Brake Lining- LF:8 mm,RF:8 mm,LR:8 mm,RR:8 mm	✓			10.7. Brake Drum Condition (general)	✓		
10.3. Brake Lines and Hoses	✓			10.8. Brake Rear Rotor- LR:9.84 mm,RR:9.89 mm	✓		
10.4. Brake System Wiring	✓			10.9. Park Brake	✓		
10.5. Brake Rotor Condition (general)	✓						

NOTES:

HAS NEW FRONT AND REAR BRAKE PADS



Section 11 - Under Vehicle

Component	P	F	NA	Component	P	F	NA
11.1. Bumpers	✓			11.5. Drive Axles / Propeller Shafts	✓		
11.2. Engine	✓			11.6. Floor Pan	✓		
11.3. Transmission / Transaxle / Transfer Case	✓			11.7. Fuel System	✓		
11.4. Differential(s)	✓			11.8. Exhaust System	✓		

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #5971126) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2026/08/26	Technician Number C5586	Facility Number 19655	Signature 
Customer Acknowledgment I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			Date (Year/Month/Day) 2026/08/26
			Customer Signature 

Invoice to Buyer



ADESA Vancouver
7111 N 8 Road
Richmond, BC V6W 1L9
(604) 232-4403
GST/HST: 896110525RT0004
PST/TVQ: PST-1012-3030

SELLER: TDAFC O/A Repo Depo

TD Auto Finance Canada Inc.

BUYER: YYC CAR RENTAL

1791 865 ALBERTA LTD

2 Robert Speck Parkway
Mississauga, ON L4Z 1H8

228 55 WESTWINDS CRESCENT NE
CALGARY, AB T3J5H2
(403) 472-0882

GST/HST: 896758042

PST/TVQ:

GST/HST: 832999171

RIN/NIP: 122965149

RIN/NIP:

CARRYING THE BEST BACKED CARS IN THE WORLD™

**10 YEAR
160,000 KM
POWERTRAIN
LTD WARRANTY™**



Province/Number: BC/13265884

Certificate of Origin: No

10-5-5 THE WARRANTY WE'RE KNOWN FOR

VEHICLE PURCHASE

Description	Amount	GST/HST	PST/TVQ	Notes
Vehicle Sale	\$11,400.00	\$570.00	\$0.00	
Buyer Fee	\$590.00	\$29.50	\$0.00	
PSI Full	\$119.00	\$5.95	\$0.00	
Mechanical Work - Parts	\$9.00	\$0.45	\$0.00	TOP UP ENGINE OIL 1L
Delivery Fee	\$729.00	\$36.45	\$0.00	
Car History Fee	\$66.55	\$3.33	\$0.00	
3rd Party F	\$115.00			
Total:	\$13,679.98	\$670.73	\$0.00	
Net Due:	\$13,679.98			



Additional charges may apply and, if applicable, will be invoiced at a later date.

PAYMENTS AND ADJUSTMENTS

Receive ACH (net)	(\$590.00) Enterprise Checkout	Receive ACH (net)	(\$66.55)	Enterprise Checkout	Receive ACH (net)	(\$729.00) Enterprise Checkout
Receive ACH (net)	(\$119.00) PSI Full	Receive ACH (net)	(\$3.33)	Enterprise Checkout	Receive ACH (net)	(\$36.45) Enterprise Checkout
Receive ACH (net)	(\$9.00) Mechanical Work - Parts	Receive ACH (net)	(\$0.45)	Enterprise Checkout	Receive ACH (net)	(\$115.00) 3rd Party F
Receive ACH (net)	(\$570.00) Buyer Fee	Receive ACH (net)	(\$0.00)	Enterprise Checkout	Receive ACH (net)	
Receive ACH (net)	(\$115.00) Car History Fee	Receive ACH (net)	(\$0.00)	Enterprise Checkout	Receive ACH (net)	
Receive ACH (net)	(\$115.00) Delivery Fee	Receive ACH (net)	(\$0.00)	Enterprise Checkout	Receive ACH (net)	
Receive ACH (net)	(\$115.00) 3rd Party F	Receive ACH (net)	(\$0.00)	Enterprise Checkout	Receive ACH (net)	
Receive ACH (net)	(\$115.00) Total	Receive ACH (net)	(\$0.00)	Enterprise Checkout	Receive ACH (net)	

This transaction is subject to the ADESA Auction Policies in effect on the date of sale and found at www.adesa.ca.