



#30 2638 Country Hills Blvd.
Calgary, AB T3N 1A7

Phone: (587) 319-5950

REPRINT CUSTOMER
INVOICE
Work Order
ST5002207

Date: 12-27-19
Page 1 of 3

Year	Make / Model	Serial Number	License	Mileage	Unit/Stock
2008	Kenworth / W900	1XKWD40XX8J934745		1732904	934745
Delivery Mileage	Delivery Date	Engine Model / Serial #	Transmission Model/Serial #		
	05-03-07	CUM ISX / 79240227	RTL0189188 / P0261795		
CPL/ARRG	Rear Ratio	Rear Axle Model / Serial #	Rear Axle Model / Serial # 2		
	3.91	D46 170 HN02717512	D46-170 HN02717513		

Engine Hours	Reefer Hours	Standby Hours	P.O. Number	Open Date / Time	Complete	Service Writer
26408.0			COD	12-20-19 / 02:20PM	12-27-19	Iar*LF

Memo

Tax ID Date: Tax ID:

1 CHECK AND REPAIR FOR HOSES ON TOP OF TRANSMISSION LEAKING.

CAUSE:

LEAKING TRANSMISSION COOLER LINES.

CORRECTION:

INSPECTED TOP OF TRANSMISSION FOR LEAK AND FOUND COOLER LINES LEAKING.

REMOVED LINES AND MEASURED TO BUILD NEW LINES. INSTALLED NEW LINES

AFTER LINES WERE BUILT. RESTRAPPED IN HEAT WRAP AND SECURED LINES.

WASHED TRANSMISSION REALLY GOOD. STARTED UNIT AND ROAD TESTED TO

CONFIRM REPAIR. NO LEAKS AT THIS TIME.

TOTAL LABOR 260.00
TOTAL PARTS 149.58

Qty	Part Number	Description	Unit	Extended
7	HR5-10	1/2 HOSE	11.98	83.86
4	884-SR528-101	45D SWIVE	16.43	65.72

2 CHECK AND REPAIR FOR DASH LIGHT ISSUES. - SEE JORDAN. NO JAKES, NO CRUISE, NO SIGNAL LIGHTS.

CAUSE:

FAULTY CECU CONTROLLER.

CORRECTION:

REMOVED CECU CONTROLLER FROM TRUCK AND SWAPPED A GOOD USED CECU

CONTROLLER TO TEST. STARTED TRUCK TO FIND GAUGES WORKING PROPERLY.

TURN SIGNALS AND CAB INTERIOR LIGHTS ALSO WORKING PROPERLY. MOVED

TRUCK OUTSIDE FOR A ROAD TEST TO CONFIRM FIX. NO WARNING LIGHTS CAME

ON AND GAUGES WORKED PROPERLY. REMOVED TEST CECU CONTROLLER AND

REINSTALLED OLD CECU CONTROLLER TOO DOWNLOAD PARAMETERS ON TO ESA.

INSTALLED NEW CECU CONTROLLER. CONNECTED ESA AND PROGRAMMED NEW CECU

CONTROLLER. APPLIED LABEL TO DASH INDICATING THE REPLACEMENT MILEAGE

AS MILEAGE IS NOT TRANSFERABLE FROM 1 CECU TO ANOTHER. REINSTALLED

DASH COMPONENTS.

TOTAL LABOR 195.00

Work Order
ST5002207

Date: 12-27-19

Page 2 of 3

TOTAL PARTS 2,222.80

Qty	Part Number	Description	Unit	Extended
1	Q21-1076-2-100	CTRL - CECU 3 CAB ELEC UN	2,222.80	2,222.80

3 REPLACE TRANSMISSION COOLER.

CAUSE:

FAULTY TRANSMISSION COOLER.

CORRECTION:

TOOK SAMPLE OF TRANSMISSION OIL AND SENT OUT TO GET TESTED. RESULTS CAME BACK WITH HIGH SODIUM CONTENT WHICH INDICATES A COOLANT LEAK AT THE COOLER. REMOVED AND REPLACED TRANSMISSION COOLER. INSTALLED NEW TRANSMISSION OIL AFTER TRANSMISSION WAS INSPECTED. FILLED COOLANT. TOPPED UP COOLANT AFTER RUNNING ENGINE AND ROAD TEST.

TOTAL LABOR 195.00
TOTAL PARTS 662.01

Qty	Part Number	Description	Unit	Extended
1	K3966	KIT-HEAT EXCHANGER	662.01	662.01

4 DRAIN TRANSMISSION OIL, REMOVE BOTTOM TRANSMISSION COVER PLATE AND INSPECT TRANSMISSION FOR WEAR.

CAUSE:

INSPECT TRANSMISSION GEARS AND BEARINGS AFTER COOLER FAILURE.

CORRECTION:

DRAINED TRANSMISSION OIL. REMOVED PTO. INSPECTED INSIDE OF TRANSMISSION, GEARS AND COUNTER SHAFT PLAY. ALL WITH IN SPEC. LOOKED AT THE MAGNETS AT THE BOTTOM OF THE TRANSMISSION. FOUND JUST NORMAL BUILD UP OF METAL ON THE MAGNETS. CLEANED PTO. REINSTALLED PTO AND CHECKED GEAR BACKLASH (0.014). FILLED UP TRANSMISSION WITH NEW OIL.

TOTAL LABOR 260.00
TOTAL PARTS 194.68

Qty	Part Number	Description	Unit	Extended
1	35P15-2	GASKET	2.08	2.08
1	35P8	GASKET COVER	3.00	3.00
15	223079-953C	CHV DELO	12.59	188.85
15	223079-953C&	ENV CHG	0.05	0.75

SHOP SUPPLIES 72.80

G.S.T. - REG. NO. R139766661RT0001 5 % OF 4,211.87 = 210.59

CUST MECH LAB-TRP 910.00
PARTS CUST R/O-TRP 3,229.07
SHOP SUPPLIES-TRP 72.80
G.S.T. R139766661RT000 210.59
T1015 CASH SALE 4,422.46

Work Order

ST5002207

Date: 12-27-19

Page 3 of 3

I ACKNOWLEDGE THAT I WILL BE RESPONSIBLE FOR ALL COST INCURRED TO DIAGNOSE, ROAD TEST, DISMANTLE AND REASSEMBLE MY UNIT IF NO FAULT CAN BE FOUND.

THE MANUFACTURER WARRANTY CONSTITUTES ALL OF THE WARRANTIES WITH RESPECT TO THE SALE OF THIS ITEM/ITEMS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESSED OR IMPLIED, INCLUDING AND IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THIS ITEM/ITEMS.

GREATWEST KENWORTH LTD. MAKES THE LIMITED WARRANTY COVERING ANY DEFECT IN WORKMANSHIP OR MATERIAL FURNISHED IN CONNECTION WITH THIS REPAIR ORDER FOR A PERIOD OF THIRTY (30) DAYS FROM THE DATE OF DELIVERY OF SAID MOTOR VEHICLE TO THE CUSTOMER/OWNER, OR 16,000 KILOMETERS WHICHEVER OCCURS FIRST.

IT IS UNDERSTOOD THAT A LIEN MAY BE PLACED THEREON FOR THE AMOUNT DUE IN CASE THE VEHICLE REPAIRS ARE NOT PAID IN FULL.

Customer: X _____ Date: _____

CALGARY -- CLAIRMONT -- LETHBRIDGE -- MEDICINE HAT -- RED DEER